

Facilities/Capital Improvement Plan Information

Document Includes:

25-27 Biennium Facilities Short List (Page 1) 10 Year Facilities Plan (Page 2-6) Facilities Capital Improvement Plan (Page 7-14) Facilities Assessment (Page 15-27)

		2025-2027 Biennium Facilities	Short List				
Facility	District/Division	Project Type	Construction Cost	Architect Design Cost	Architect Construction Cost	Total Cost	
Towner Section Building	Minot	Building	\$2,854,882	-	\$74,475	\$2,929,357	Projects
Dickinson Truck Barn	Dickinson	Building	\$5,603,011	-	\$111,510	\$5,714,521	for \$15.5
Bowbells Section Building	Williston	Building	\$2,854,882	-	\$74,475	\$2,929,357	Million
Rolla Section Building	Devils Lake	Building	\$3,376,447	-	\$88,081	\$3,464,528	Budget
		2025-2027 Biennium Sub Total	\$14,689,222	-	\$348,541	\$15,037,763	
Ellendale Section Building	Valley City	Building	\$2,333,317	-	\$60,869	\$2,394,186	
Garrison Section Building	Minot	Building	\$2,854,882	-	\$74,475	\$2,929,357	
Lake Agassiz Rest Area	Fargo	Remodel/Parking Lot	\$5,500,000	\$655,460	\$200,303	\$6,355,763	
Alexander Henry Rest Area	Grand Forks	Remodel/Parking Lot	\$5,000,000	\$718,245	\$150,518	\$5,868,763	
Devils Lake Truck Barn 2	Devils Lake	Building	\$2,280,163	-	\$53,200	\$2,333,363	
Minot Truck Barn	Minot	Addition	\$3,321,545	-	\$109,942	\$3,431,487	
Dickinson Materials Lab	Dickinson	Remodel	\$305,009	Included with Di	ckinson Truck Barn	\$305,009	
Minot Materials Lab	Minot	Remodel	\$244,007	Included with	Minot Truck Barn	\$244,007	
Bismarck District Office Design	Bismarck	Building	-	\$572,886	-	\$572,886	
Selfridge Section Building Design	Bismarck	Building	-	\$182,607	-	\$182,607	
Wyndemere Section Building Design	Fargo	Building	-	\$182,607	-	\$182,607	
Bowman Section Building Design	Dickinson	Building	-	\$223,426	-	\$223,426	
Adams Section Building Design	Grand Forks	Building	-	\$182,607	-	\$182,607	
Watford City Section Building Design	Williston	Building	-	\$264,244	-	\$264,244	
Medina / Crystal Springs Rest Area Design	Valley City	Building/Parking Lot	-	\$990,000	-	\$990,000	
		2025-2027 Biennium Total	\$36,528,145	\$3,972,082	\$997,848	\$41,498,075	

Facility	Facility Type	District/Division	Year Built/Updat ed/Acquire d	Update	Existing Building (dimension s & size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase 1	Caution Condition Phase 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed
Dickinson Materials Lab	Headquarters	Dickinson		25-27								Capital improvement projects and costs included with Dickinson Office.
Minot Materials Lab	Headquarters	Minot		25-27								Needed capital improvement projects and costs included with Minot Office.
Danger & Alarm Condition Projects	Improvement Projects	Statewide		25-27								
District Headquarter Site Plans	Improvement Projects	Statewide		25-27								
Grand Forks Construction Office	Miscellaneous Building	Grand Forks	1976	25-27	3,200	\$50,000						Building renovation and roof replacement.
Hailstone Creek Visitor Center EB	Rest Area	Bismarck	1996	25-27	2,443						\$525,000	See needed capital improvement projects in Rest Area Improvement sheet.
Hailstone Creek Visitor Center EB Truck Parking Improvement	Rest Area	Bismarck		25-27								
Hailstone Creek Visitor Center WB	Rest Area	Bismarck	1996	25-27	2,933						\$525,000	See needed capital improvement projects in Rest Area Improvement sheet.
Hailstone Creek Visitor Center WB Truck Parking Improvemen	Rest Area	Bismarck		25-27								
Lake Agassiz Visitor Center	Rest Area	Fargo	1996	25-27	2,662						\$434,750	See needed capital improvement projects in Rest Area Improvement sheet.
Lake Agassiz Visitor Center Truck Parking Improvement	Rest Area	Fargo		25-27								
Towner Section Building	Section Building	Minot	1973	25-27	2,400						\$1,054,100	Hot water heater, unit heaters, internal lighting, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, environmental, structural, water supply in, and waste water removal.
Bowbells Section Building 1	Section Building	Williston	1969	25-27	2,400							Paint shop floor, water heater, office furniture, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence, repair columns, replace tin, overhead doors, overhead door framing, bathroom remodel, shop heat, replace floor, hvac, walk in door, internal lighting, sheetrock, shelving/racks, and yard grading. New storage shed (20' x 30').
Bowbells Section Building 2	Section Building	Williston		25-27							\$25,000	Lighting, bathroom ceiling, and pressure washer vent.
Ellendale Section Building	Section Building	Valley City	1968	25-27	2,400							Hot water heater, external lighting, electrical distribution, plumbing fixtures, interior doors, exterior doors, metal roofing system, metal cladding, interior concrete, site drainage, and larger connection to city water.
Garrison Section Building	Section Building	Minot	1974	25-27	2,400						\$467,250	Hot water heater, unit heaters, internal lighting, electrical controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, environmental, and south wall replacement.
Bowman Section Building	Section Building	Dickinson	1985	25-27	3,800	\$71,300	\$71,300	\$121,300	\$71,300	\$71,300		Interior concrete, plumbing fixtures, wall sheeting, water heater, recovery heaters, electrical system, interior doors, overhead doors and openers, exterior doors, wall sheeting, overhead door framing, windows, gutters, exterior concrete, sand/oil separator, drain field, security system, purchase lot in industrial park, pump and water tank for truck washing, storage building, new water line. Construct salt brine containment, estimated \$20,000, and new salt brine tanks, estimated \$50,000.
Adams Section Building	Section Building	Grand Forks	1966	25-27	2,400	\$20,000					\$292,750	External lighting, unit heaters, electrical distribution, metal roofing system, metal cladding, interior concrete, and septic tank.
Rolla Section Building	Section Building	Devils Lake	1989	25-27	3,750	\$100,000		\$118,500	\$82,000	\$34,000		Exterior doors, metal cladding, metal roofing system, structural, and interior doors. Replacement with larger facility, maintenance or rear structural beams, new lighting, new walk-in door, shingles on office or steel roof, expand office size. Standby generator.
Dickinson Truck Barn	Truck Barn	Dickinson	NA	25-27								
Minot Truck Barn	Truck Barn	Minot	2006	25-27	9,600			\$7,500				Replace ceiling exhaust fans/motors.
Devils Lake Truck Barn 2	Truck Barn	Devils Lake		25-27								Build one.
Panger Weigh Station	Weigh Station	Williston		25-27								



Facility	Facility Type	District/Division	Year Built/Upda ed/Acquire d	Undate	Existing Building (dimension s & size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Caution Condition Phase 1 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed
Bismarck Office	Headquarters	Bismarck		27-29	7,344	\$167,815	\$83,907			\$1,426,428	See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: office furniture, ADA lift replacement, parking lot repair and seal coat, security system, and MDU line move.
Valley City Materials Lab	Headquarters	Valley City	1976	27-29	27,189						Needed capital improvement projects and costs included with Valley City Office.
Alert Condition Phase 1 Projects	Improvement Projects	Statewide		27-29							
Elm River Visitor Center NB	Rest Area	Fargo	2003	27-29	2,617	\$22,475				\$202,275	See needed capital improvement projects in Rest Area Improvement sheet.
Elm River Visitor Center NB Truck Parking Improvement	Rest Area	Fargo		27-29							
Elm River Visitor Center SB	Rest Area	Fargo	2003	27-29	2,617	\$22,475				\$202,275	See needed capital improvement projects in Rest Area Improvement sheet.
Elm River Visitor Center SB Truck Parking Improvement	Rest Area	Fargo		27-29							Lagoon Inspection
Alexander Henry Visitor Center	Rest Area	Grand Forks	1997	27-29	1,693	\$50,000				\$450,000	See needed capital improvement projects in Rest Area Improvement sheet.
Alexander Henry Visitor Center Truck Parking Improvement	Rest Area	Grand Forks		27-29							
Bismarck District Salt Brine Building 2	Salt Brine Building	Bismarck	NA	27-29							
Devils Lake District Salt Brine Building 2	Salt Brine Building	Devils Lake	NA	27-29			\$5,000				Relocate approximately 400' of 1/0 URD 220 Mil XLP Jkt cable.
Dickinson District Salt Brine Building 2	Salt Brine Building	Dickinson	NA	27-29							
Fargo Salt Brine Building 2	Salt Brine Building	Fargo	NA	27-29							
Grand Forks District Salt Brine Building 2	Salt Brine Building	Grand Forks	NA	27-29							
Minot District Salt Brine Building 2	Salt Brine Building	Minot	NA	27-29							
Valley City District Salt Brine Building 2	Salt Brine Building	Valley City	NA	27-29							
Williston District Salt Brine Building 2	Salt Brine Building	Williston	NA	27-29							
Selfridge Section Building	Section Building	Bismarck	1967	27-29	2,400	\$133,310				\$1,199,790	Hot water heater, unit heaters, internal lighting, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, environmental, structural, water supply in, and waste water removal.
Wyndemere Section Building	Section Building	Fargo	1974	27-29	2,400	\$155,285				\$1,397,565	Bunham boiler, in-floor heat, hot water pumps, hot water heater, hvac system, internal lighting, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, structural, water supply in, and waste water removal.
Watford City Section Building	Section Building	Williston	2001	27-29	5,000	*\$68,390				*\$645,510	Paint shop floor, water heater, office furniture, flooring, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence, hvac, roof insulation, office addition, office flooring, and electrical upgrades. New storage shed (20' x 30'). Add 2 salt water tanks and containment, yard grading, and shelving/racks.
Mohall Section Building	Section Building	Minot	1975	27-29	2,400	\$68,567				\$620,000	Hot water heater, unit heaters, internal lighting, external lighting, electrical controls, electrical distribution, electrical to generator, plumbing fixtures, exterior doors, windows, metal roofing system, metal cladding, interior concrete, structural, environmental, and waste water removal.
Maddock Section Building	Section Building	Devils Lake	1967	27-29	2,400	\$115,300				\$1,037,700	Metal roofing system, metal cladding, and increase water line size. Additional replacement or improvement items needed without building replacement: 2: water line, standby generator, exterior doors, hvac system, internal lighting, external lighting, electric controls, electrical distribution, interior doors, exterior concrete, interior concrete, and structural.
Ashley Section Building	Satellite Section Building	Valley City	1963	27-29	2,400	\$35,000				\$591,950	Remodel bathroom, concrete apron, internal lighting, electrical distribution, interior doors, overhead doors, metal roofing system, metal cladding, interior concrete, environmental, structural, and holding tank and drain field for sanitary system.
Bismarck Truck Barn	Truck Barn	Bismarck		27-29	23,000				\$185,000		Exterior concrete.
Fargo Truck Barn	Truck Barn	Fargo	2013	27-29	18,000						
West Fargo Weigh Station	Weigh Station	Fargo		27-29						\$30,000	New fencing around lagoon.



Facility	Facility Type	District/Division	Year Built/Updat ed/Acquire d	Update	Existing Building (dimension s & size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase (Caution Condition Phase 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed
Minot Office	Headquarters	Minot		29-31	26,795	\$11,900	\$439,850	\$549,850	\$389,425	\$419,425		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: remodel construction staff area, sidewalks around headquarters, and outside skin replacement.
Minot Shop	Headquarters	Minot		29-31	26,795	\$150,000						Needed capital improvement projects and costs included with Minot Office. Additional capital improvement project needed: air conditioning.
Williston Office	Headquarters	Williston	1976	29-31	20,974	\$493,000	\$141,725	\$141,725	\$74,375	\$114,375		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: asbestos removal, dismantle old material slab, soundproof bathrooms, cubicles, administrative furniture, fixtures, and equipment, heated DEF shed for fuel island, yard landscaping, approach into headquarters, remove tower, parking lot, fence, security camera, heated sidewalks and lawn sprinkler system.
Williston Shop	Headquarters	Williston	1976	29-31	20,974	\$225,000						Needed capital improvement projects and costs included with Williston Office. Additional capital improvement projects needed: walk in doors, air conditioning, work benches, air compressor relocation, floor drains, auxiliary heat, and flooring.
Alert Condition Phase 2 Projects	Improvement Projects	Statewide		29-31								
Crystal Springs Rest Area EB	Rest Area	Valley City	1966	29-31	1,173	\$28,000	\$28,000				\$224,000	See needed capital improvement projects in Rest Area Improvement sheet.
Medina Rest Area WB	Rest Area	Valley City	1995	29-31	1,296	\$28,000	\$28,000				\$224,000	See needed capital improvement projects in Rest Area Improvement sheet.
Killdeer Section Building 1	Section Building	Dickinson	1971	29-31	2,400	*\$47,800	*\$47,800	*\$47,800	*\$47,800	*\$47,800		Plumbing fixtures, office flooring, office air conditioner, recovery heaters, boiler, ventilation system, interior doors, overhead doors and openers, exterior doors, roof, windows, gutters, security system, propane tank, slab, fence, and exterior concrete. Construct salt brine containment, estimated \$20,000, and new salt brine tanks, estimated \$50,000. Repair and improvement costs included in construction costs for addition.
Killdeer Section Building 2	Section Building	Dickinson	2005	29-31	3,000							See Killdeer Section Building 1 for needed repairs and improvements.
Underwood Section Building 1	Section Building	Bismarck	1973	29-31	2,400			\$295,750	\$77,500	\$114,200		Internal lighting, hvac system, exterior doors, external lighting, and overhead doors.
Underwood Section Building 2	Section Building	Bismarck	2005	29-31	2,500							See Underwood Section Building 1 for needed repairs and improvements.
Casselton Section Building 1	Section Building	Fargo	1974	29-31	2,400	\$30,000		\$35,050	\$1,218,800	\$92,000		Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, interior concrete, structural, water supply in, and waste water removal.
Casselton Section Building 2	Section Building	Fargo	2003	29-31	2,500							See Casselton Section Building 1 for needed repairs and improvements.
Cavalier Section Building	Section Building	Grand Forks	1964	29-31	2,400	\$46,225					\$416,025	Unit heaters, internal lighting, electric controls, electrical distribution, metal roofing system, metal cladding, and septic tank. Construct salt brine containment at new site, estimated \$15,000.
Flasher Section Building	Section Building	Bismarck	1970	29-31	2,400	\$62,060	\$62,060				\$937,080	Increase waterline size. Possible replacement or improvement items needed before building replacement: unit heaters, hvac system, electric controls, electrical distribution, exterior doors, overhead doors, windows, metal roofing system, metal cladding, interior concrete, structural, water supply in, and waste water removal.
Lisbon Section Building	Section Building	Fargo	1971	29-31	2,400	\$158,818	\$158,818				\$1,193,715	Parking lot work for CDL testing, Bunham boiler, hot water pumps, hot water heater, unit heaters, hvac system, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, structural, water supply in, and waste water removal.
Oakes Satellite Section Building	Satellite Section Building	Valley City	1964	29-31	2,400	\$50,000					\$545,200	Remodel bathroom, replace furnace, replace walk in doors, replace windows, and new concrete apron. Additional replacement or improvement items needed without building replacement: electrical distribution, interior doors, overhead doors, metal roofing system, metal cladding, interior concrete, and structural.
Pekin Section Building	Satellite Section Building	Devils Lake	1966	29-31	2,400	\$39,000					\$520,000	Connect to city sewer system and external lighting. Additional replacement or improvement items needed without building replacement: door opener system, drain field, windows, exterior concrete, structural, metal roofing system, increase water line size, metal cladding, and interior concrete.
Grand Forks Truck Barn	Truck Barn	Grand Forks	2003	29-31	9,600	\$10,000			\$107,500	\$66,200		Exterior doors, overhead doors and openers, and door fobs.
Jamestown Truck Barn	Truck Barn	Valley City	2003	29-31	8,800	\$65,000	\$10,000	\$10,000	\$255,050	\$230,000		Concrete floor drains, connect to city sewer system, parking lot improvements, and overlay hot bit pvmt.
Joliette Weigh Station	Weigh Station	Grand Forks		29-31							\$100,000	Remove rutted asphalt pavement and repave.



Facility	Facility Type	District/Division	Year Built/Updat ed/Acquire d	I Undate	Existing Building (dimension s & size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase 1	Caution Condition Phase 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed
Devils Lake Office	Headquarters	Devils Lake	1976	31-33	6,476	\$208,900	\$208,900				\$1,671,200	See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: new humidifier
Devils Lake Shop	Headquarters	Devils Lake	1976	31-33	21,520	\$257,350	\$107,350				\$858,800	for heating system. Parking lot reconstruction Capital improvement projects and costs included with Devils Lake Office. Additional capital improvement projects needed: electric furnace for bathrooms and sign shop office, electric controls, domestic plumbing fixtures, interior doors, exterior doors, overhead shop doors, windows, exterior concrete, parking lot reconstruction, brick structure, larger water line, and air conditioning.
Grand Forks Materials Lab	Headquarters	Grand Forks		31-33								
Grand Forks Office	Headquarters	Grand Forks		31-33		\$287,650	\$1,117,125	\$1,117,125	\$35,250	\$25,250		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: Admin office common area new carpet.
Caution Condition Phase 1 Projects	Improvement Projects	Statewide		31-33								
Apple Creek Visitor Center EB	Rest Area	Bismarck	1999	31-33	2,617	\$22,500	\$22,500	\$22,500			\$157,500	See needed capital improvement projects in Rest Area Improvement sheet.
Apple Creek Visitor Center WB	Rest Area	Bismarck	1999	31-33	2,660	\$22,500	\$22,500	\$22,500	D		\$157,500	See needed capital improvement projects in Rest Area Improvement sheet.
Beach Visitor Center	Rest Area	Dickinson	2001	31-33	3,500	\$26,075	\$26,075	\$26,075	5		\$182,525	See needed capital improvement projects in Rest Area Improvement sheet.
Velva Section Building	Section Building	Minot	1990	31-33	3,750		\$30,000		\$128,000	\$159,250		Internal lighting, external lighting, septic tank, exterior doors, overhead doors, windows, interior concrete, environmental, water supply in, and waste water removal. New office addition, 40' addition for equipment.
Forman Section Building	Section Building	Fargo	1967	31-33	2,400	\$24,714	\$24,714	\$24,714	1		\$1,408,708	Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, wat supply in, and waste water removal.
Stanley Section Building	Section Building	Williston	2001	31-33	6,000	\$232,080	\$252,080	\$232,080	\$252,080	\$232,080		Paint shop floor, water heater, office furniture, flooring, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling fan exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence, toile bathroom flooring, office addition, floor heat, hvac, external lighting, interior doors, unit heaters, and electrical distribution. New storage shed (2 x 30'). Add 2 salt water tanks, containent, yard grading, and shelving/racks.
Michigan Section Building	Section Building	Grand Forks	2000	31-33	4.800	\$20,000			\$30,000	\$24,750		Overhead door openers, door fobs, and unit heaters. Repair concrete floor with epoxy coating to fix scaling.
Hettinger Section Building	Section Building	Dickinson	2016	31-33	5,400	\$800	\$800	\$46,300		\$800		Office air conditioner, smart thermostat, gas line and exhaust for pressure washer, propane tank, slab, and fence, security system, and water heater.
New Town Section Building	Section Building	Williston	2013	31-33	6,750	\$232,080	\$252,080	\$232,080	\$252,080	\$232,080		Paint shop floor, water heater, office furniture, flooring, yard grading, shelving/racks, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence, toilet, bathroom flooring, office addition, floor heat, hvac, external lighting, interior doors, unit heaters, and electrical distribution. New storage shed (20' x 30').
Linton Section Building	Section Building	Bismarck	1989	31-33	3,750	\$30,000		\$67,750	\$110,000	\$54,750		Unit heaters, internal lighting, external lighting, windows, interior concrete, structural, water supply in, and waste water removal.
Courtenay Satellite Section Building	Satellite Section Building	Valley City	1966	31-33	2,400	\$45,000					\$478,100	Remodel bathroom, overhead doors, concrete apron, sanitary sewer storage tank, hot water heater, electrical distribution, metal roofing system metal cladding, interior concrete, environmental, structural, and larger waterline.
Mayville Satellite Section Building	Satellite Section Building	Fargo	1968	31-33	2,400	\$151,285					\$1,361,565	Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, structural, water supply in, and waste water removal.
Richardton Satellite Section Building	Satellite Section Building	Dickinson	1969	31-33	2,400	\$14,000					\$71,000	Office air conditioner, ventilation system, exterior wall sheeting, sill plate, gutters, gas line and exhaust for pressure washer, security system, and smart thermostat. Construct salt brine containment, estimated \$20,000, and new salt brine tanks, estimated \$50,000.



Facility	Facility Type	District/Division	Year Built/Upda ed/Acquire d	I Undate	Existing Building (dimension s & size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase 1		Additional Needed se Repairs without New Building Building
Bismarck Shop	Headquarters	Bismarck		33-35	27,200	\$225,000	\$166,063	\$166,063	\$405,875	\$405,875	75 See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: paint exterior air conditioning, auto shop concrete floor.
Grand Forks Shop	Headquarters	Grand Forks		33-35		\$255,000					Needed capital improvement projects and costs included with Grand Forks Office. Additional capital improvement project needed: shop crane replacement and air conditioning. Remodol the bathrooms, shop foremans office, locker room and parts room.
Valley City Office	Headquarters	Valley City	1976	33-35	27,189	\$268,100	\$366,000	\$366,000	\$89,500	\$89,500	See needed capital improvement projects in NDDOT Buildings Assessment sheet. Parking lot improvements to both concrete and hot bit pavement, repair subgrade issues, inventory storage area improvements
Valley City Shop	Headquarters	Valley City	1976	33-35	27,189	\$270,000					Needed capital improvement projects and costs included with Valley City Office. Additional capital improvement project needed: exterior concr wall paint or seal, replace overhead and walk in doors, and air conditioning.
Caution Condition Phase 2 Projects	Improvement Projects	Statewide		33-35							
Crary Rest Area	Rest Area	Devils Lake	1995	33-35	2,233	\$30,000	\$30,000	\$30,000	\$30,000		\$180,000 See needed capital improvement projects in Rest Area Improvement sheet.
Larimore Rest Area	Rest Area	Grand Forks	2000	33-35	462	\$50,000	\$50,000	\$50,000	\$50,000		\$300,000 See needed capital improvement projects in Rest Area Improvement sheet.
Edgeley Rest Area	Rest Area	Valley City	1996	33-35	854	\$27,000	\$27,000	\$27,000	\$27,000		\$162,000 See needed capital improvement projects in Rest Area Improvement sheet.
Jamestown Visitor Center EB	Rest Area	Valley City	2000	33-35	2,617	\$30,000	\$30,000	\$30,000	\$30,000		\$180,000 See needed capital improvement projects in Rest Area Improvement sheet.
Jamestown Visitor Center EB Truck Parking Improvement	Rest Area	Valley City		33-35							
Jamestown Visitor Center WB	Rest Area	Valley City	2000	33-35	2,617	\$30,000	\$30,000	\$30,000	\$30,000		\$180,000 See needed capital improvement projects in Rest Area Improvement sheet.
Jamestown Visitor Center WB Truck Parking Improvement	Rest Area	Valley City		33-35							
Fessenden Satellite Section Building	Satellite Section Building	Devils Lake	1968	33-35	2,400	\$97,925					\$881,325 Internal lighting, electrical distribution, plumbing fixtures, exterior doors, windows, metal roofing system, metal cladding, interior concrete, increase water line size, connect to city sewer, add oil/sand separator, hanging unit heaters, internal lighting, structural issues, overhead doors, and exterior concrete.
Finley Satellite Section Building	Satellite Section Building	Grand Forks	1969	33-35	2,400	\$35,000					Septic tank, exterior outlets, and overhead door seals.
Gackle Satellite Section Building	Satellite Section Building	Valley City	1971	33-35	2,400	\$10,000					\$417,000 Windows, electrical distribution, interior doors, metal roofing system, metal cladding, and larger connection to city water.
Litchville Satellite Section Building	Satellite Section Building	Valley City	1967	33-35	2,400	\$40,000					\$263,000 Remodel bathroom, overhead doors, concrete apron, external lighting, metal roofing system, metal cladding, interior concrete, and structural.
New England Satellite Section Building	Satellite Section Building	Dickinson	1973	33-35	2,400	\$26,200					\$281,800 Interior concrete, plumbing fixtures, interior lighting, office flooring, office air conditioner, interior wall sheeting, water heater, infrared heaters electrical system, ventilation system, interior doors, overhead door and openers, exterior doors, exterior wall sheeting, roof, sill plate, overhead door framing, windows, gutters, exterior concrete, sand/oil separator, drain field, propane tank, slab, fence, and smart thermostat.



Facility	Facility Type	District/Division	Year Built/Updated /Acquired	Projected Update Biennium	Existing Building (size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase 1	Caution Condition Phase 2	Additional Needed Repairs without New Building	
Bismarck Materials Lab	Headquarters	Bismarck	2023									
Bismarck Office	Headquarters	Bismarck		27-29	7,344	\$167,815	\$83,907				\$1,426,428	See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: office
												furniture, ADA lift replacement, parking lot repair and seal coat, security system, and MDU line move.
Bismarck Shop	Headquarters	Bismarck		33-35	27,200	\$225,000	\$166,063	\$166,063	\$405,875	\$405,875		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: paint
C + low		0 1 1000				6025.425	¢222.500	daaa 500	4555 000	\$0.000		exterior, air conditioning, auto shop concrete floor.
Central Office	Headquarters	Central Office				\$936,425	\$223,500	\$223,500	\$555,000	\$8,000		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: elevator modernization project (\$547,000), bollards and concrete (\$42,000), and repair and cleaning of limestone (\$286,425).
Interim Traffic Management Center	Headquarters	Central Office		23-25								
Devils Lake Materials Lab	Headquarters	Devils Lake					\$150,000					Needed capital improvement projects and costs included with Devils Lake Office. Additional capital improvement project needed: remodel the
												district materials lab.
Devils Lake Office	Headquarters	Devils Lake	1976	31-33	6,476	\$208,900	\$208,900					See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: new humidifier for heating system. Parking lot reconstruction
Devils Lake Shop	Headquarters	Devils Lake	1976	31-33	21,520	\$257,350	\$107,350				\$858,800	Capital improvement projects and costs included with Devils Lake Office. Additional capital improvement projects needed: electric furnace for bathrooms and sign shop office, electric controls, domestic plumbing fixtures, interior doors, exterior doors, overhead shop doors, windows, exterior concrete, parking lot reconstruction, brick structure, larger water line, and air conditioning.
Dickinson Materials Lab	Headquarters	Dickinson		25-27								Capital improvement projects and costs included with Dickinson Office.
Dickinson Office	Headquarters	Dickinson				\$1,327,500	\$342,500	\$342,500	\$277,500	\$277,500		See capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: roof replacement, fuel island replacement, concrete CDL pad, cast iron pipe replacement, ventilation system, foundation repair, security system, generator, chain link fence around remaining headquarters ,replace entryway and storage room heaters, replace office air conditioners, replace heat pumps, office flooring and paint, replace retaining wall and fence, parkign lot mill, HBP, valley gutter and C&G, replace windows, office exterior doors and frames, reapir and seal exterior brick, smart thermostats where we don't have, relocate storeroom, replace van bodies with cold storage
Dickinson Shop	Headquarters	Dickinson				\$150,000						Capital improvement projects and costs included with Dickinson Office. Additional capital improvement project needed: air conditioning.
Fargo Materials Lab	Headquarters	Fargo	2020									See needed capital improvement projects in NDDOT Buildings Assessment sheet.
Fargo Office	Headquarters	Fargo			30,729	\$650,000	\$697,250	\$697,250	\$161,950	\$161,950		See capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: roof replacement. Parking lot Mill and Overlay tied to Fargo Shop
Fargo Shop	Headquarters	Fargo			30,729	\$360,000				\$250,000		Needed capital improvement projects and costs included with Fargo Office. Additional capital improvement projects needed: roof replacement, shop ventilation system upgrade, air conditioning, and double door replacement. Parking lot Mill and Overlay
Grand Forks Materials Lab	Headquarters	Grand Forks		31-33								
Grand Forks Office	Headquarters	Grand Forks		31-33		\$287,650	\$1,117,125	\$1,117,125	\$35,250	\$25,250		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement project needed: Admin office
Grand Forks Shop	Headquarters	Grand Forks		33-35		\$255,000						common area new carpet. Needed capital improvement projects and costs included with Grand Forks Office. Additional capital improvement project needed: shop crane replacement and air conditioning. Remodol the bathrooms, shop foremans office, locker room and parts room.
Materials & Research Office	Headquarters	Materials & Research	2023	23-25	20,655					\$350,000		New parking lot
Minot Materials Lab	Headquarters	Minot		25-27						+200,000		Needed capital improvement projects and costs included with Minot Office.
Minot Office	Headquarters	Minot		29-31	26,795	\$11,900	\$439,850	\$549,850	\$389,425	\$419,425		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: remodel construction staff area, sidewalks around headquarters, and outside skin replacement.
Minot Shop	Headquarters	Minot		29-31	26,795	\$150,000						Needed capital improvement projects and costs included with Minot Office. Additional capital improvement project needed: air conditioning.
Valley City Materials Lab	Headquarters	Valley City	1976	27-29	27,189							Needed capital improvement projects and costs included with Valley City Office.
Valley City Office	Headquarters	Valley City	1976	33-35	27,189	\$268,100	\$366,000	\$366,000	\$89,500	\$89,500		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Parking lot improvements to both concrete and hot bit pavement, repair subgrade issues, inventory storage area improvements
Valley City Shop	Headquarters	Valley City	1976	33-35	27,189	\$270,000						Needed capital improvement projects and costs included with Valley City Office. Additional capital improvement project needed: exterior concrete wall paint or seal, replace overhead and walk in doors, and air conditioning.
Williston Materials Lab	Headquarters	Williston	1980		6,000							
Williston Office	Headquarters	Williston	1976	29-31	20,974	\$493,000	\$141,725	\$141,725	\$74,375	\$114,375		See needed capital improvement projects in NDDOT Buildings Assessment sheet. Additional capital improvement projects needed: asbestos removal, dismantle old material slab, soundproof bathrooms, cubicles, administrative furniture, fixtures, and equipment, heated DEF shed for fuel island, yard landscaping, approach into headquarters, remove tower, parking lot, fence, security camera, heated sidewalks and lawn sprinkler system.
Williston Shop	Headquarters	Williston	1976	29-31	20,974	\$225,000						Needed capital improvement projects and costs included with Williston Office. Additional capital improvement projects needed: walk in doors, air conditioning, work benches, air compressor relocation, floor drains, auxiliary heat, and flooring.
Williston Sign Shop	Headquarters	Williston	1980		6,000	\$20,000						Shelving, racks, secure cage, lighting, work bench, and walk in doors.
Alert Condition Phase 1 Projects	Improvement Projects	Statewide		27-29								
Alert Condition Phase 2 Projects	Improvement Projects	Statewide		29-31								
Caution Condition Phase 1 Projects Caution Condition Phase 2 Projects	Improvement Projects Improvement Projects	Statewide Statewide		31-33 33-35								
Danger & Alarm Condition Projects	Improvement Projects	Statewide		25-27								
District Headquarter Fire Alarm Systems	Improvement Projects	Statewide		23-27								
District Headquarter Site Plans	Improvement Projects	Statewide		25-27								
Devils Lake Driver License	Driver License	Driver License										
Dickinson Driver License & Motor Vehicle	Driver License	Driver License										
Fargo Driver License	Driver License	Driver License	2021									
Grand Forks Driver License	Driver License	Driver License										Needed capital improvement projects and costs included with Grand Forks Office.
Jamestown Driver License Minot Driver License	Driver License Driver License	Driver License Driver License	2021									
Williston Driver License	Driver License Driver License	Driver License Driver License	2021		2,290							
williston Driver License	Driver License	Driver License	2020		2,290							



	1		1	1	1			1			
			Year	Projected	Existing	Danger & Alarm	Alert Condition A	lert	Caution	Caution Additional Needed	
Facility	Facility Type	District/Division	Built/Updated	Update	Building	Condition	Phase 1		Condition Phase C	ondition Phase Repairs without Nev	w Improvement and Repair Projects Needed
			/Acquired	Biennium	(size)	condition	Pha	ase 2	1	2 Building	
Bismarck Traffic & Radio Shop Building	Miscellaneous Building	Bismarck	1976		6,000				\$150,000		Windows, Insulation, Roof, Doors
Bismarck Traffic Storage Building	Miscellaneous Building	Bismarck								\$480,000	*New storage building for 4 counting vehicles and Pathways Van.
Bismarck Warehouse	Miscellaneous Building	Bismarck	1976			\$150,000			\$15,000		Reskin outside of building and insulate inside. Add overhead door for Pathways Van access.
Grand Forks Construction Office	Miscellaneous Building		1976	25-27	3,200	\$50,000					Building renovation and roof replacement.
Grand Forks Sign Shop	Miscellaneous Building		2003		3,420	\$29,750					See needed capital improvement projects in NDDOT Buildings Assessment sheet.
Arnegard Radio Tower Building	Radio Tower Building		1962		480	\$50,000					Generator replacement.
Blaisdell Radio Tower Building	Radio Tower Building		2016		384						
Bottineau Radio Tower Building	Radio Tower Building		2013 2016		384 384						
Bowman Radio Tower Building Carrington Radio Tower Building	Radio Tower Building Radio Tower Building		2016		384						
Cayuga Radio Tower Building	Radio Tower Building		2014		384						-
Cleveland Radio Tower Building	Radio Tower Building		2014		384						
Columbus Radio Tower Building	Radio Tower Building		2013		384						
Denhoff Radio Tower Building	Radio Tower Building		1962		352						
Devils Lake Radio Tower Building	Radio Tower Building	_	1962		480						
Dickinson Radio Tower Building	Radio Tower Building	Maintenance	1962		480						
Dogden Butte Radio Tower Building	Radio Tower Building		2014		384						
Driscoll Radio Tower Building	Radio Tower Building		2014		384						
Esmond Radio Tower Building	Radio Tower Building		2015		384						
Fargo Radio Tower Building	Radio Tower Building		2013		384						
Finley Radio Tower Building	Radio Tower Building		2014		384		\$20,000				
Fortuna Radio Tower Building	Radio Tower Building		2014		384		420.222				
Grand Forks Radio Tower Building	Radio Tower Building		1962		480		\$20,000				
Hannaford Radio Tower Building	Radio Tower Building	_	2013		384		\$20,000				
Hannover Radio Tower Building Hillsboro Radio Tower Building	Radio Tower Building Radio Tower Building		2013 2016		384 384						
Killdeer Radio Tower Building	Radio Tower Building		2016		384						
Linton Radio Tower Building	Radio Tower Building		1962		200						
Marmath Radio Tower Building	Radio Tower Building		2015		384						
Merricourt Radio Tower Building	Radio Tower Building		2016		384						
Milton Radio Tower Building	Radio Tower Building		1962		352		\$20,000				
Minot Radio Tower Building	Radio Tower Building		2016		384		, 2,222				
Mohall Radio Tower Building	Radio Tower Building	Maintenance	2016		384						
Mott Radio Tower Building	Radio Tower Building		2014		384						
Mylo Radio Tower Building	Radio Tower Building		2013		384						
New Leipzig Radio Tower Building	Radio Tower Building		2007		138						
New Salem Radio Tower Building	Radio Tower Building		2016		384						
Peer Creek Radio Tower Building	Radio Tower Building		2016		384		4				
Petersburg Radio Tower Building	Radio Tower Building		2013		384		\$20,000				
Raleigh Radio Tower Building	Radio Tower Building		2016 2016		384 384						
Ryder Radio Tower Building Sentinel Butte Radio Tower Building	Radio Tower Building Radio Tower Building		2016		384						
Tioga Radio Tower Building	Radio Tower Building		1962		352	\$125,000					Building and generator replacement.
Valley City Radio Tower Building	Radio Tower Building		1962		544	\$123,000					bunding and generator replacement.
Wahpeton Radio Tower Building	Radio Tower Building	_	2014		384						
Wales Radio Tower Building	Radio Tower Building		2012		384						
Westfield Radio Tower Building	Radio Tower Building		2016		384						
Williston Radio Tower Building	Radio Tower Building		1962		480	\$125,000					Building and generator replacement.
Wishek Radio Tower Building	Radio Tower Building	Maintenance	2013		384						
Apple Creek Visitor Center EB	Rest Area	Bismarck	1999	31-33	2,617	\$22,500		\$22,500		\$157,50	0 See needed capital improvement projects in Rest Area Improvement sheet.
Apple Creek Visitor Center WB	Rest Area	Bismarck	1999	31-33	2,660	\$22,500	\$22,500	\$22,500			0 See needed capital improvement projects in Rest Area Improvement sheet.
Hailstone Creek Visitor Center EB	Rest Area	Bismarck	1996	25-27	2,443					\$525,00	0 See needed capital improvement projects in Rest Area Improvement sheet.
Hailstone Creek Visitor Center EB Truck Parking Improvemen		Bismarck		25-27							
Hailstone Creek Visitor Center WB	Rest Area	Bismarck	1996	25-27	2,933					\$525,00	0 See needed capital improvement projects in Rest Area Improvement sheet.
Hailstone Creek Visitor Center WB Truck Parking Improveme		Bismarck Davils Lake	1005	25-27	2 222	620.000	620.000	¢20.000	¢20.000	A400.00	O See needed emital improvement available in Doct Ava- Investment to be at
Crary Rest Area	Rest Area	Devils Lake	1995	33-35	2,233	\$30,000		\$30,000	\$30,000		0 See needed capital improvement projects in Rest Area Improvement sheet.
Beach Visitor Center Western ND Visitor Center	Rest Area Rest Area	Dickinson Dickinson	2001	31-33	3,500	\$26,075	\$26,075	\$26,075		\$182,52	5 See needed capital improvement projects in Rest Area Improvement sheet.
Elm River NB Utility Shed	Rest Area	Fargo	2020								Needed capital improvement projects and costs included with Elm River Visitor Center NB.
Elm River SB Utility Shed	Rest Area	Fargo	2020								Needed capital improvement projects and costs included with Elm River Visitor Center NB. Needed capital improvement projects and costs included with Elm River Visitor Center NB.
Elm River Visitor Center NB	Rest Area	Fargo	2003	27-29	2,617	\$22,475				\$202.27	5 See needed capital improvement projects in Rest Area Improvement sheet.
Elm River Visitor Center NB Truck Parking Improvement	Rest Area	Fargo		27-29		, , , , ,				, 102)27	
Elm River Visitor Center SB	Rest Area	Fargo	2003	27-29	2,617	\$22,475				\$202,27	See needed capital improvement projects in Rest Area Improvement sheet.
Elm River Visitor Center SB Truck Parking Improvement	Rest Area	Fargo		27-29							Lagoon Inspection
Fargo I-29 Visitor Center	Rest Area	Fargo					\$30,000				Lagoon Inspection
Lake Agassiz Visitor Center	Rest Area	Fargo	1996	25-27	2,662					\$434,75	0 See needed capital improvement projects in Rest Area Improvement sheet.
Lake Agassiz Visitor Center Truck Parking Improvement	Rest Area	Fargo		25-27							
Lynchberg Rest Area	Rest Area	Fargo	2000		48	\$200,000	\$114,750				See needed capital improvement projects in Rest Area Improvement sheet. Lagoon Inspection
Mapleton Rest Area	Rest Area	Fargo	2000		48	\$200,000	\$114,750				See needed capital improvement projects in Rest Area Improvement sheet. Lagoon Inspection
Alexander Henry Shed	Rest Area	Grand Forks	2016								Needed capital improvement projects and costs included with Alexander Henry Visitor Center.



	1										
			Year	Projected	Existing	Danger & Alarm Al	ert Condition	Alert	Caution	Caution	Additional Needed
Facility	Facility Type	District/Division	Built/Updated /Acquired	Update Biennium	Building (size)	Condition	Phase 1	Condition Phase 2	Condition Phase	Condition Phase	Repairs without New Improvement and Repair Projects Needed Building
	-		-			4		FildSe Z	1		
Alexander Henry Visitor Center Alexander Henry Visitor Center Truck Parking Improvement	Rest Area	Grand Forks Grand Forks	1997	27-29 27-29	1,693	\$50,000					\$450,000 See needed capital improvement projects in Rest Area Improvement sheet.
Larimore Rest Area	Rest Area	Grand Forks	2000		462	\$50,000	\$50,000	\$50,000	\$50,000		\$300,000 See needed capital improvement projects in Rest Area Improvement sheet.
Larimore Rest Area Shed	Rest Area	Grand Forks	2016	00 00	102	\$30,000	\$50,000	ψ30,000	ψουρουσ		Needed capital improvement projects and costs included with Larimore Rest Area.
Crystal Springs Rest Area EB	Rest Area	Valley City	1966	29-31	1,173	\$28,000	\$28,000				\$224,000 See needed capital improvement projects in Rest Area Improvement sheet.
Crystal Springs Rest Area EB - Storage Shed	Rest Area	Valley City									Connect power to building.
Edgeley Rest Area	Rest Area	Valley City	1996	33-35	854	\$27,000	\$27,000	\$27,000	\$27,000		\$162,000 See needed capital improvement projects in Rest Area Improvement sheet.
Edgeley Rest Area - Storage Shed Jamestown Visitor Center EB	Rest Area	Valley City	2000	33-35	2,617	\$30,000	\$30,000	\$30,000	\$30,000		C100 000 Co. and ded annited improvement projects in Part Area Improvement sheet
Jamestown Visitor Center EB Jamestown Visitor Center EB Truck Parking Improvement	Rest Area Rest Area	Valley City Valley City	2000	33-35	2,017	\$30,000	\$30,000	\$30,000	\$30,000		\$180,000 See needed capital improvement projects in Rest Area Improvement sheet.
Jamestown Visitor Center WB	Rest Area	Valley City	2000	33-35	2,617	\$30,000	\$30,000	\$30,000	\$30,000		\$180,000 See needed capital improvement projects in Rest Area Improvement sheet.
Jamestown Visitor Center WB Truck Parking Improvement	Rest Area	Valley City		33-35							
Medina Rest Area WB	Rest Area	Valley City	1995	29-31	1,296	\$28,000	\$28,000				\$224,000 See needed capital improvement projects in Rest Area Improvement sheet.
Medina Rest Area WB - Storage Shed	Rest Area	Valley City									Connect power to building.
Oriska Rest Area Charl	Rest Area	Valley City	1991	23-25	1,600						See needed capital improvement projects in Rest Area Improvement sheet.
Oriska Rest Area Shed Oriska Rest Area Truck Parking Improvement	Rest Area Rest Area	Valley City Valley City	NA	23-25							Needed capital improvement projects and costs included with Oriska Rest Area.
Oriska Vending Shelter	Rest Area	Valley City	2002	23 23	275						Needed capital improvement projects and costs included with Oriska Rest Area.
Bismarck District Salt Brine Building 2	Salt Brine Building			27-29							
Bismarck Salt Brine Building	Salt Brine Building		2019		960						
Devils Lake District Salt Brine Building 2	Salt Brine Building			27-29			\$5,000				Relocate approximately 400' of 1/0 URD 220 Mil XLP Jkt cable.
Devils Lake Salt Brine Building	Salt Brine Building		2020		960	400.500	400.000	400.000	400.000	400.000	
Beulah Salt Brine Facility	Salt Brine Building	Dickinson	1976		2,400	\$22,600	\$22,600	\$22,600	\$22,600	\$22,600	Wall sheeting, water heater, infrared heater, electrical system, overhead doors and openers, exterior doors, roof, overhead door frames, and exterior concrete.
Dickinson District Salt Brine Building 2	Salt Brine Building			27-29	000		A40.00-				Consider Contract and the other Contract and
Dickinson Salt Brine Building Fargo Salt Brine Building	Salt Brine Building Salt Brine Building		2020 2019		960 512		\$10,000				Security System, autowater shutoff
Fargo Salt Brine Building 2	Salt Brine Building	-		27-29	512						
Hillsboro Salt Brine Shed	Salt Brine Building		1999		561						
Drayton Salt Brine Shed	Salt Brine Building		2000		168	\$50,000					Brine containment and concrete apron.
Grand Forks District Salt Brine Building 2	Salt Brine Building	Grand Forks	NA	27-29							
Grand Forks Salt Brine Building	Salt Brine Building		2019		960						
Grand Forks Salt Brine Shed	Salt Brine Building		2000	27.20	192						
Minot District Salt Brine Building 2 Minot Salt Brine Building	Salt Brine Building Salt Brine Building		NA 2019	27-29	960		\$8,000				Replace electric heaters
Valley City District Salt Brine Building 2	Salt Brine Building			27-29	300		\$8,000				Replace electric fleaters
Valley City Salt Brine Building	Salt Brine Building		2020		960						
New Town Salt Brine Building	Salt Brine Building	Williston				\$30,000					2" waterline.
Stanley Salt Brine Building	Salt Brine Building	Williston				\$45,000					2" waterline, roof, siding, overhead door, heater, and concrete apron.
Williston District Salt Brine Building 2	Salt Brine Building		NA 2020	27-29	000						
Williston Salt Brine Building Bismarck Salt Building	Salt Brine Building Salt Building		2020		960 10,000						
Bismarck Salt Shed	Salt Building		1995		9,216						
Center Salt Building	Salt Building	Bismarck	2009		2,880	\$60,000					Move to new section yard or Replace with New Building.
Flasher Salt Building			2011		3,600						
Glen Ullin Salt Building	Salt Building		2014		7,200						
Linton Salt Building	Salt Building		2011		3,600 3,200						
McClusky Salt Building Napoleon Salt Building	Salt Building Salt Building		2014		3,600						
Selfridge Salt Building	Salt Building		2011		3,600						
Steele Salt Building	Salt Building	Bismarck	2013		7,000						
Underwood Salt Building	Salt Building		2014		7,200						
Cando Salt Building	Salt Building		2011		3,600		\$2,000		\$15,000		Power and flood light, extended apron.
Carrington Salt Building	Salt Building		2011		3,600 10,000				\$15,000		Extended apron.
Devils Lake Salt Building Hurdsfield Salt Shed	Salt Building Salt Building		2013 1999		640			\$7,000	\$150,000		New roof, flood lights and power. New overhead door.
Langdon Salt Building	Salt Building		2014		3,600		\$2,000	\$7,000			Filod light.
Maddock Salt Building	Salt Building		2014		3,600		+2,000				
Pekin Salt Building	Salt Building	Devils Lake	2014		3,600		\$2,500				Electric power and flood lights.
Rolla Salt Building	Salt Building		2011		3,600		\$2,000		\$15,000		Add power and flood light, extend apron.
Rugby Salt Building	Salt Building		2014		7,200		\$2,000		40= 00=		Rain gutter on east side to solve the water issue.
Beach Salt Building Belfield Salt Building	Salt Building Salt Building		2013		3,600 3,600				\$25,000 \$25,000		pave floor and approach
Beulah Salt Building	Salt Building		2011		3,600				\$25,000		pave floor and approach pave floor and approach
Bowman Salt Building	Salt Building		2012		3,600				\$25,000		pave floor and approach
Dickinson Salt Building	Salt Building		2010		10,400			\$300,000			Replace cables, trusses, fabric, add fabric wall and doors for east side.
Hettinger Salt Building	Salt Building		2014		3,600				\$25,000		pave floor and approach
Killdeer Salt Building	Salt Building		2014		3,600				\$25,000		pave floor and approach
Mott Salt Building	Salt Building		2012		3,600				\$25,000		pave floor and approach
New England Salt Building	Salt Building	Dickinson	2013		1,600				\$25,000		pave floor and approach



Casselton Salt Building Fargo Salt Building Forman Salt Building Hillsboro Salt Building Salt Building Lidgerwood Salt Building Lisbon Salt Building Salt Building Mayville Salt Building Salt Building Wahpeton Salt Building Wandemere Salt Building	Facility Type alt Building alt Building	Fargo	Year Built/Updated /Acquired 2014 2012 1995 2011 2011 2011 2014 2014 2014	Projected Update Biennium 23-25	Existing Building (size) 3,600 3,600 9,216 3,600 3,600 3,600 3,600 3,600	Danger & Alarm Condition	Phase 1	Alert Condition Phase 2	Caution Condition Phase (1 \$25,000	Caution Condition Phase I 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed pave floor and approach
Richardton Salt Building Casselton Salt Building Fargo Salt Building Forman Salt Building Hillsboro Salt Building Lidgerwood Salt Building Lisbon Salt Building	alt Building	Dickinson Fargo	/Acquired 2014 2012 1995 2011 2011 2011 2014 2014	Biennium	(size) 3,600 3,600 9,216 3,600 3,600 3,600	Condition	Phase 1		1		Building	
Casselton Salt Building Fargo Salt Building Forman Salt Building Forman Salt Building Fillsboro Salt Building	alt Building lalt Building	Fargo	2012 1995 2011 2011 2011 2014 2014 2014	23-25	3,600 9,216 3,600 3,600 3,600				\$25,000			pave floor and approach
Casselton Salt Building Fargo Salt Building Forman Salt Building Forman Salt Building Forman Salt Building Forman Salt Building	alt Building lalt Building	Fargo	2012 1995 2011 2011 2011 2014 2014 2014	23-25	3,600 9,216 3,600 3,600 3,600				\$23,000			pave noor and approach
Fargo Salt Building Forman Sal	alt Building	Fargo	1995 2011 2011 2011 2014 2014 2014	23-25	9,216 3,600 3,600 3,600							
Forman Salt Building Hillsboro Salt Building Lidgerwood Salt Building Lisbon Salt Building	alt Building lalt Building	Fargo Fargo Fargo Fargo Fargo Fargo Fargo Grand Forks	2011 2011 2011 2014 2014 2014		3,600 3,600 3,600							
Lidgerwood Salt Building Sa Lisbon Salt Building Sa Mayville Salt Building Sa Wahpeton Salt Building Sa Wyndemere Salt Building Sa Adams Salt Building Sa Cavalier Salt Building Sa Cooperstown Salt Building Sa Drayton Salt Building Sa Finley Salt Building Sa	alt Building lalt Building	Fargo Fargo Fargo Fargo Fargo Grand Forks	2011 2014 2014 2014		3,600							
Lisbon Salt Building Mayville Salt Building Wahpeton Salt Building Wyndemere Salt Building Adams Salt Building Salt Building Cavalier Salt Building Cooperstown Salt Building Drayton Salt Building	alt Building lalt Building	Fargo Fargo Fargo Fargo Grand Forks	2014 2014 2014									
Mayville Salt Building Wahpeton Salt Building Salt Building Wyndemere Salt Building Adams Salt Building Salt Building Cavalier Salt Building Cooperstown Salt Building Drayton Salt Building Salt Building Salt Building Salt Building Salt Building Salt Building	alt Building lalt Building lalt Building lalt Building lalt Building lalt Building	Fargo Fargo Fargo Grand Forks	2014 2014		3.600							
Wahpeton Salt Building Wyndemere Salt Building Adams Salt Building Salt Building Cavalier Salt Building Cooperstown Salt Building Drayton Salt Building Salt Building Salt Building Salt Building Salt Building Salt Building	alt Building alt Building alt Building alt Building alt Building alt Building	Fargo Fargo Grand Forks	2014									
Wyndemere Salt Building Salt Adams Salt Building Salt Buil	alt Building alt Building alt Building alt Building	Fargo Grand Forks			3,600							
Adams Salt Building Salt Build	alt Building alt Building alt Building	Grand Forks			3,600							
Cavalier Salt Building Salt Cooperstown Salt Building	alt Building alt Building		2014		10,800							
Cooperstown Salt Building Sa Drayton Salt Building Sa Finley Salt Building Sa	alt Building	Crand Farks	2014	-	3,600 3,600	¢60,000	-		-			Many self-huilding to now section site
Drayton Salt Building Salt Bui			2012		3,600	\$60,000						Move salt building to new section site.
Finley Salt Building Sa			2014		7,000	\$75,000						Concrete apron.
	alt Building		2002		1,040	\$25,000						Roof repair.
	alt Building		2012		3,600	\$23,000						New louvered wall vents on ends of building. Add perimeter fence with rolling gates to the southwest quadrant of District lot where the salt
					,,,,,,,							building is to create security for District inventory.
Grand Forks Salt Building Sa	alt Building	Grand Forks	1997		12,160							
	alt Building		2011		3,600							
	alt Building		2011		3,600	\$25,000			\$60,000			Roof repair and move building to site of section building.
	alt Building		1996		640							
,	alt Building		2011		3,600				\$25,000			add rain troughs to roof line, replace damaged roof panels.
•	alt Building		2012		3,600				\$10,000			add rain troughs to roof line
	alt Building		2012		3,600			Ć10.000	\$10,000			add new rain troughs to roof line
	alt Building		2015	-	3,600 10,000			\$10,000				replace ceiling panels and add rain troughs to roof line
	alt Building alt Building		2013		3,600				\$10,000			add rain troughs to roof line
	alt Building		2012	+	3,600		-		\$10,000			add rain troughs to roof line
	alt Building		2015		3,600				\$10,000			add rain troughs to roof line
	ialt Building		2013		1,600			\$10,000	720,000			add rain troughs to roof line
	ialt Building	Valley City					\$50,000	. ,				Replace building, ag tractors do not fit in current building.
Courtenay Salt Shed Sa	alt Building	Valley City	1976		1,122		\$50,000					Replace building, ag tractors do not fit in current building.
Edgeley Salt Building Sa	ialt Building	Valley City	2011		3,600							
Ellendale Salt Building Sa	alt Building		2011		3,600							
	alt Building		1976		1,122		\$50,000					Replace building, ag tractors do not fit in current building.
	alt Building		2012		10,000		4	\$30,000				Replace cables, replace steel bottom end member, and patch and repair tarp cover
	alt Building		1976		1,316		\$50,000					Replace building, ag tractors do not fit in current building.
	alt Building alt Building		2012 1976		3,600 1,089		\$50,000					Deplace building ag tractors do not fit in current building
	Falt Building		2012		7,000		\$30,000	\$20,000				Replace building, ag tractors do not fit in current building. Replace cables.
	Salt Building		2014	+	3,600		-	\$20,000				replace causes.
	Salt Building		2012		3,000		\$40,000					Lighting, concrete apron, and containment lighting.
	alt Building		2014		3,600		\$40,000					Lighting, concrete apron, and containment lighting.
New Town Salt Building Sa	alt Building	Williston	2012				\$45,000					Lighting, concrete apron,containment lighting, and second load out pump system.
Stanley Salt Building Sa	alt Building	Williston	2014		7,200		\$45,000					Lighting, concrete apron,containment lighting, and second load out pump system.
	alt Building		2012				\$45,000					Lighting, concrete apron,containment lighting, and second load out pump system.
	alt Building		2012				\$45,000					Lighting, concrete apron,containment lighting, and second load out pump system.
	alt Building		2016		10,000		\$45,000					Lighting, concrete apron,containment lighting, and second load out pump system.
	Section Building		1984	23-25	3,800		\$10,000					Security system, smart thermostat
Grafton Section Building Se	Section Building	Grand Forks	1972	23-25	2,400						\$312,800	Internal lighting, external lighting, unit heaters, electric controls, plumbing fixtures, exterior doors, metal cladding, and interior concrete
Center Section Building	Section Building	Bismarck	1995	23-25	3,200							
	Section Building	Fargo	1973	23-25	2,400						\$1,400,815	Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, electric controls, electrical distribution, plumbing
Lidger wood Section Building	ection building	Taigo	1973	23-23	2,400							fixtures, interior doors, exterior doors, overhead doors, windows, metal cladding, exterior concrete, interior concrete, structural, and water
												supply in.
Towner Section Building Se	Section Building	Minot	1973	25-27	2,400						\$1,054,100	Hot water heater, unit heaters, internal lighting, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors,
												exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, environmental, structura
												water supply in, and waste water removal.
Bowbells Section Building 1 Se	ection Building	Williston	1969	25-27	2,400						\$1,191,850	Paint shop floor, water heater, office furniture, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling fans, extended
												electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence, repair
												columns, replace tin, overhead doors, overhead door framing, bathroom remodel, shop heat, replace floor, hvac, walk in door, internal lighting
												sheetrock, shelving/racks, and yard grading. New storage shed (20' x 30').
	ection Building	Williston	1000	25-27	0.105							Lighting, bathroom ceiling, and pressure washer vent.
Ellendale Section Building Se	ection Building	Valley City	1968	25-27	2,400						\$642,650	Hot water heater, external lighting, electrical distribution, plumbing fixtures, interior doors, exterior doors, metal roofing system, metal claddi
Corrigon Costion Building	Costion Duilding	Minat	1074	25.27	2.400						6467.050	interior concrete, site drainage, and larger connection to city water.
Garrison Section Building Se	ection Building	Minot	1974	25-27	2,400							Hot water heater, unit heaters, internal lighting, electrical controls, electrical distribution, plumbing fixtures, interior doors, exterior doors,
												overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, environmental, and south wall replacement.



							1				1	
			Year	Projected	Existing	Danger & Alarm	Alert Condition	Alert	Caution	Caution	Additional Needed	
Facility	Facility Type	District/Division	Built/Updated	-	Building	Condition	Phase 1	1	Condition Phase		Repairs without New	Improvement and Repair Projects Needed
			/Acquired	Biennium	(size)			Phase 2	1	2	Building	
Bowman Section Building	Section Building	Dickinson	1985	25-27	3,800	\$71,300	\$71,300	\$121,300	\$71,300	\$71,300		Interior concrete, plumbing fixtures, wall sheeting, water heater, recovery heaters, electrical system, interior doors, overhead doors and
												openers, exterior doors, wall sheeting, overhead door framing, windows, gutters, exterior concrete, sand/oil separator, drain field, security
												system, purchase lot in industrial park, pump and water tank for truck washing, storage building, new water line. Construct salt brine
												containment, estimated \$20,000, and new salt brine tanks, estimated \$50,000.
Adams Section Building	Section Building	Grand Forks	1966	25-27	2,400	\$20,000					\$292,750	External lighting, unit heaters, electrical distribution, metal roofing system, metal cladding, interior concrete, and septic tank.
Selfridge Section Building	Section Building	Bismarck	1967	27-29	2,400	\$133,310					\$1,199,790	Hot water heater, unit heaters, internal lighting, external lighting, electric controls, electrical distribution, plumbing fixtures, interior doors,
												exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, environmental, structural, water supply in, and waste water removal.
Wyndemere Section Building	Section Building	Fargo	1974	27-29	2,400	\$155,285					\$1,397,565	Bunham boiler, in-floor heat, hot water pumps, hot water heater, hvac system, internal lighting, external lighting, electric controls, electrical
												distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, structural, water supply in, and waste water removal.
Watford City Section Building	Section Building	Williston	2001	27-29	5,000	*\$68,390					*\$645,510	Paint shop floor, water heater, office furniture, flooring, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling
,											, ,	fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence
												hvac, roof insulation, office addition, office flooring, and electrical upgrades. New storage shed (20' x 30'). Add 2 salt water tanks and
											4	containment, yard grading, and shelving/racks.
Mohall Section Building	Section Building	Minot	1975	27-29	2,400	\$68,567					\$620,000	Hot water heater, unit heaters, internal lighting, external lighting, electrical controls, electrical distribution, electrical to generator, plumbing
												fixtures, exterior doors, windows, metal roofing system, metal cladding, interior concrete, structural, environmental, and waste water removal.
Killdeer Section Building 1	Section Building	Dickinson	1971	29-31	2,400	*\$47,800	*\$47,800	*\$47,800	*\$47,800	*\$47,800		Plumbing fixtures, office flooring, office air conditioner, recovery heaters, boiler, ventilation system, interior doors, overhead doors and openers,
												exterior doors, roof, windows, gutters, security system, propane tank, slab, fence, and exterior concrete. Construct salt brine containment,
												estimated \$20,000, and new salt brine tanks, estimated \$50,000. Repair and improvement costs included in construction costs for addition.
Killdeer Section Building 2	Section Building	Dickinson	2005	29-31	3,000			4005 550	4== ===	4444.000		See Killdeer Section Building 1 for needed repairs and improvements.
Underwood Section Building 1	Section Building	Bismarck	1973	29-31	2,400			\$295,750	\$77,500	\$114,200		Internal lighting, hvac system, exterior doors, external lighting, and overhead doors.
Underwood Section Building 2	Section Building	Bismarck	2005	29-31	2,500	400.000		405.050	44.040.000	400.000		See Underwood Section Building 1 for needed repairs and improvements.
Casselton Section Building 1	Section Building	Fargo	1974	29-31	2,400	\$30,000		\$35,050	\$1,218,800	\$92,000		Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, external lighting, electric controls, electrical
												distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, interior concrete,
Consider Continue Duilding 2	Castina Pullalia	F	2002	20.24	2.500							structural, water supply in, and waste water removal.
Casselton Section Building 2	Section Building	Fargo	2003 1964	29-31 29-31	2,500 2,400	\$46,225					¢416.025	See Casselton Section Building 1 for needed repairs and improvements.
Cavalier Section Building	Section Building	Grand Forks	1964	29-31	2,400	\$40,225					\$410,025	Unit heaters, internal lighting, electric controls, electrical distribution, metal roofing system, metal cladding, and septic tank. Construct salt brine containment at new site, estimated \$15,000.
Flasher Section Building	Section Building	Bismarck	1970	29-31	2,400	\$62,060	\$62,060				\$937.080	Increase waterline size. Possible replacement or improvement items needed before building replacement: unit heaters, hvac system, electric
	3				,	, - ,	, , , , , , ,				, , , , , , ,	controls, electrical distribution, exterior doors, overhead doors, windows, metal roofing system, metal cladding, interior concrete, structural,
												water supply in, and waste water removal.
Lisbon Section Building	Section Building	Fargo	1971	29-31	2,400	\$158,818	\$158,818	3			\$1,193,715	Parking lot work for CDL testing, Bunham boiler, hot water pumps, hot water heater, unit heaters, hvac system, external lighting, electric
												controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal
												cladding, exterior concrete, interior concrete, structural, water supply in, and waste water removal.
Velva Section Building	Section Building	Minot	1990	31-33	3,750		\$30,000		\$128,000	\$159,250)	Internal lighting, external lighting, septic tank, exterior doors, overhead doors, windows, interior concrete, environmental, water supply in, and
		_				4	4				4	waste water removal. New office addition, 40' addition for equipement.
Forman Section Building	Section Building	Fargo	1967	31-33	2,400	\$24,714	\$24,714	\$24,714			\$1,408,708	Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, electric controls, electrical distribution, plumbing
												fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, water supply in, and waste water removal.
Stanley Section Building	Section Building	Williston	2001	31-33	6,000	\$232,080	\$252,080	\$232,080	\$252,080	\$232,080		Paint shop floor, water heater, office furniture, flooring, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling
												fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence
												toilet, bathroom flooring, office addition, floor heat, hvac, external lighting, interior doors, unit heaters, and electrical distribution. New storage
												shed (20' x 30'). Add 2 salt water tanks, contaiment, yard grading, and shelving/racks.
Michigan Section Building	Section Building	Grand Forks	2000	31-33	4,800	\$20,000			\$30,000	\$24,750		Overhead door openers, door fobs, and unit heaters. Repair concrete floor with epoxy coating to fix scaling.
Hettinger Section Building	Section Building	Dickinson	2016	31-33	5,400	\$800	\$800	\$46,300	\$10,800	\$800		Office air conditioner, smart thermostat, gas line and exhaust for pressure washer, propane tank, slab, and fence, security system, and water
	0.01.0.11.1		2012	21.00		4000 000	40-000	4000 000	4050 000	4000 000		heater.
New Town Section Building	Section Building	Williston	2013	31-33	6,750	\$232,080	\$252,080	\$232,080	\$252,080	\$232,080		Paint shop floor, water heater, office furniture, flooring, yard grading, shelving/racks, fixtures, and equipment, concrete apron, work bench,
												shelving, air plumbing, ceiling fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2"
												waterline, oil change pit, fence, toilet, bathroom flooring, office addition, floor heat, hvac, external lighting, interior doors, unit heaters, and
Linton Section Building	Section Building	Bismarck	1989	31-33	3,750	\$30,000		\$67,750	\$110,000	\$54,750		electrical distribution. New storage shed (20' x 30'). Unit heaters, internal lighting, external lighting, windows, interior concrete, structural, water supply in, and waste water removal.
Emon Section Building	Section Building	District	1505	31 33	3,730	430,000		\$67,730	7110,000	<i>454,750</i>		one reacts, mental ignality, executal ignality, windows, interior concrete, structural, water supply in, and waste water removal.
Cando Section Building	Section Building	Devils Lake	2018		7,650		\$120,000)				Maintenance trial on floor and maintenance and possible replacement of remaining concrete interior. Standby generator, finish sealing the
Corrington Costion Pull-line	Continue Duil II	Dovils Labo	2005		0.000		620.000	677.500	ATE 000	64.42.000		remaining portion of the shop floor.
Carrington Section Building	Section Building	Devils Lake	2005		8,000		\$30,000	\$77,500	\$75,000	\$142,000	,	2" waterline into building, office addition, exterior doors, external lighting, plumbing fixtures, generator, exterior concrete, exhaust fan, A/C, an overhead doors.
Glen Ullin Section Building	Section Building	Bismarck	2006		8,400							
McClusky Section Building	Section Building	Bismarck	1981		7,500	\$150,000			\$5,050	\$518,750		Replace interior concrete and add in-floor heat, replace interior skin, plumbing fixtures, unit heaters, hvac system, exterior concrete, and water
												supply in.
Napoleon Section Building	Section Building	Bismarck	2000		4,800			\$30,000	\$30,000	\$16,750		Water supply in, waste water removal, and internal lighting.
Steele Section Building	Section Building	Bismarck Davils Lake	2012		7,800			¢40F.000	\$60,000	602.000		Water supply in and waste water removal.
Langdon Section Building	Section Building	Devils Lake	2001 1967	27.20	6,000 2,400	¢11F 200		\$185,000	\$60,000	\$62,000		Exterior concrete, increase water line size, septic system, oil/sand separator, generator, and interior concrete.
Maddock Section Building	Section Building	Devils Lake	1907	27-29	2,400	\$115,300					\$1,037,700	Metal roofing system, metal cladding, and increase water line size. Additional replacement or improvement items needed without building
												replacement: 2: water line, standby generator, exterior doors, hvac system, internal lighting, external lighting, electric controls, electrical
												distribution, interior doors, exterior concrete, interior concrete, and structural.



Facility	Facility Type	District / Division	Year	Projected	Existing Building	Danger & Alarm	Alert Condition	Alert	Caution	Caution	Additional Needed	Improvement and Densir Designer Nondad
racility	Facility Type	District/Division	Built/Updated /Acquired	Update Biennium	(size)	Condition	Phase 1	Condition Phase 2	1	ondition Phase	Repairs without New Building	Improvement and Repair Projects Needed
Polla Section Puilding	Section Building	Dovils Lako		25-27	<u> </u>	\$100,000			\$2,000	\$34,000		Exterior dears, motal cladding, motal reading system, structural, and interior dears. Penlacement with larger facility, maintenance or rear
Rolla Section Building	Section Building	Devils Lake	1989	23-27	3,750	\$100,000		\$118,500	\$82,000	334,000		Exterior doors, metal cladding, metal roofing system, structural, and interior doors. Replacement with larger facility, maintenance or rear structural beams, new lighting, new walk-in door, shingles on office or steel roof, expand office size. Standby generator.
Rugby Section Building	Section Building	Devils Lake	2015		10,500					\$185,000		Exterior concrete. Replace ceiling fans, 2" water line to other side of shop, service humidistat system. On-demand hot water heater.
Belfield Section Building	Section Building	Dickinson	2006		8,400	\$54,000	\$54,000	\$54,000	\$54,000	\$54,000		Trench drain, smart thermostat, plumbing fixtures, recovery heaters, boiler, ventilation system, interior doors, overhead doors and openers, exterior doors, exterior concrete, security system, drive through tow plow bay, 2" water line.
Beulah Section Building	Section Building	Dickinson	2006		7,200	\$37,000	\$37,000	\$37,000	\$37,000	\$37,000		Trench drain, plumbing fixtures, water heater, overhead doors and openers, exterior doors, windows, exterior concrete, gas line and exhaust for pressure washer, replace propane tank, recovery heaters, security system
Mott Section Building	Section Building	Dickinson	2005		7,000	\$65,200	\$65,200	\$65,200	\$65,200	\$65,200		Trench drain, plumbing fixtures, water heater, boiler, ventilation system, interior doors, overhead doors and openers, exterior doors, roof, windows, gutters, pump and water tank for truck washing, drain field, propane tank, slab, fence, security system, replace overhead door concrete thresholds, and exterior concrete. Construct salt brine containment, estimated \$20,000, and new salt brine tanks, estimated \$50,000.
Hillsboro Section Building	Section Building	Fargo	2017		10,260							
Wahpeton Section Building 1	Section Building	Fargo	2003		6,000		\$130,000		\$5,050			Water supply in, waster water removal, and plumbing fixtures.
Wahpeton Section Building 2	Section Building	Fargo	1972									See Wahpeton Section Building 1 for needed repairs and improvements.
Cooperstown Section Building	Section Building	Grand Forks	2016		5,400		\$40,000		\$30,000			Wash water tank, door openers, and door fobs. Repair concrete floor with epoxy coating to fix scaling.
Drayton Section Building	Section Building	Grand Forks	2007		9,600		\$20,000					Overhead door openers and door fobs.
Larimore Section Building	Section Building	Grand Forks	2012		7,200	400.000	\$20,000		440.000			Overhead door openers and door fobs.
Bottineau Section Building	Section Building	Minot	2012		6,000	\$30,000	Ć4 000	ć200	\$10,000			Electrical work for generator connection and exterior doors. Concrete jacking for apron
Harvey Section Building	Section Building	Minot	2015		7,500	\$20,500	\$1,000	\$200				Electrical work for generator connection, hot water heater, plumbing fixtures, and exterior doors.
Kenmare Section Building	Section Building	Minot	1999		6,120	\$20,000	ć2.400	\$30,000		dc2 000		Electrical work for generator connection, plumbing fixtures, water heater, exterior doors, and windows replacement.
Parshall Section Building	Section Building	Minot	2003		6,000	\$20,000	\$3,100	\$77,500	,	\$62,000		Electrical work for generator connection, hot water heater, exterior doors, and interior concrete.
Edgeley Section Building Moding Section Building	Section Building	Valley City	2021		5,400 7,000	\$50,000 \$20,000	\$125,000	\$15,000	\$3,100	\$299,200		Move brine containment/system to new building site. Remove old system at North yard. Add permanent propane generator.
Medina Section Building	Section Building	Valley City	2004		7,000	\$20,000	\$125,000	\$15,000	\$3,100	\$299,200		Connect to city sewer system, increase water line size, replace office windows, replace walk in doors, convert loft to breakroom, hot water heater, external lighting, overhead doors, and exterior concrete.
Wishek Section Building	Section Building	Valley City	2012		6,000	\$10,000				\$137,000		Walk in doors, overhead doors, and interior concrete.
Crosby Section Building	Section Building	Williston	2004		7,000	\$138,320	\$158,320	\$138,320	\$158,320	\$138,320		Paint shop floor, water heater, office furniture, flooring, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling
						, 33/3	, , , , ,	,,	, , , , ,	,,.		fans, exterior electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, fence internal lighting, external lighting, waste water removal, hvac, and interior concrete. New storage shed (20' x 30'). Shop floor inlay, yard grading, shelviing/racks.
Tioga Section Building	Section Building	Williston	2009		6,750	\$64,580	\$84,580	\$64,580	\$74,580	\$64,580		Paint shop floor, water heater, office furniture, fixtures, and equipment, concrete apron, work bench, shelving, air plumbing, ceiling fans, exterio electrical outlets, wash curtain, SWPPP dike, pressure washer vent, used oil storage, floor drains, 2" waterline, oil change pit, and fence. New storage shed (20' x 30'). yard grading, shelving/racks.
Ashley Section Building	Satellite Section Building	Valley City	1963	27-29	2,400	\$35,000					\$591,950	Remodel bathroom, concrete apron, internal lighting, electrical distribution, interior doors, overhead doors, metal roofing system, metal cladding, interior concrete, environmental, structural, and holding tank and drain field for sanitary system.
Courtenay Satellite Section Building	Satellite Section Building	Valley City	1966	31-33	2,400	\$45,000					\$478,100	Remodel bathroom, overhead doors, concrete apron, sanitary sewer storage tank, hot water heater, electrical distribution, metal roofing system metal cladding, interior concrete, environmental, structural, and larger waterline.
Fessenden Satellite Section Building	Satellite Section Building	Devils Lake	1968	33-35	2,400	\$97,925						Internal lighting, electrical distribution, plumbing fixtures, exterior doors, windows, metal roofing system, metal cladding, interior concrete, increase water line size, connect to city sewer, add oil/sand separator, hanging unit heaters, internal lighting, structural issues, overhead doors, and exterior concrete.
Finley Satellite Section Building	Satellite Section Building	Grand Forks	1969	33-35	2,400	\$35,000						Septic tank, exterior outlets, and overhead door seals.
Gackle Satellite Section Building	Satellite Section Building	Valley City	1971	33-35	2,400	\$10,000					\$417,000	Windows, electrical distribution, interior doors, metal roofing system, metal cladding, and larger connection to city water.
Halliday Satellite Section Building	Satellite Section Building	Dickinson	1972		2,400	\$26,300	\$26,300	\$26,300	\$26,300	\$26,300		Interior concrete, plumbing fixtures, interior wall sheeting, water heater, infrared heaters, electrical system, interior doors, overhead doors and openers, exterior doors, roof, overhead door framing, gutters, exterior concrete, generator, sand/oil separator, and drain field or connect to city sewer, security system, generato, and smart thermostat.
Litchville Satellite Section Building	Satellite Section Building	Valley City	1967	33-35	2,400	\$40,000					\$263,000	Remodel bathroom, overhead doors, concrete apron, external lighting, metal roofing system, metal cladding, interior concrete, and structural.
Mayville Satellite Section Building	Satellite Section Building	Fargo	1968	31-33	2,400	\$151,285						Bunham boiler, in-floor heat, hot water pumps, hot water heater, unit heaters, hvac system, electric controls, electrical distribution, plumbing fixtures, interior doors, exterior doors, overhead doors, windows, metal roofing system, metal cladding, exterior concrete, interior concrete, structural, water supply in, and waste water removal.
New England Satellite Section Building	Satellite Section Building	Dickinson	1973	33-35	2,400	\$26,200						Interior concrete, plumbing fixtures, interior lighting, office flooring, office air conditioner, interior wall sheeting, water heater, infrared heaters, electrical system, ventilation system, interior doors, overhead door and openers, exterior doors, exterior wall sheeting, roof, sill plate, overhead door framing, windows, gutters, exterior concrete, sand/oil separator, drain field, propane tank, slab, fence, and smart thermostat.
Oakes Satellite Section Building	Satellite Section Building	Valley City	1964	29-31	2,400	\$50,000						Remodel bathroom, replace furnace, replace walk in doors, replace windows, and new concrete apron. Additional replacement or improvement items needed without building replacement: electrical distribution, interior doors, overhead doors, metal roofing system, metal cladding, interior concrete, and structural.
Pekin Section Building	Satellite Section Building	Devils Lake	1966	29-31	2,400	\$39,000					\$520,000	O Connect to city sewer system and external lighting. Additional replacement or improvement items needed without building replacement: door opener system, drain field, windows, exterior concrete, structural, metal roofing system, increase water line size, metal cladding, and interior concrete.
Richardton Satellite Section Building	Satellite Section Building	Dickinson	1969	31-33	2,400	\$14,000					\$71,000	Office air conditioner, ventilation system, exterior wall sheeting, sill plate, gutters, gas line and exhaust for pressure washer, security system, and smart thermostat. Construct salt brine containment, estimated \$20,000, and new salt brine tanks, estimated \$50,000.
Starkweather Satellite Section Building	Satellite Section Building	Devils Lake	1966		2,400			\$338,700	\$810,550	\$62,000		Hanging unit heaters, internal lighting, external lighting, overhead doors, metal roofing system, metal cladding, increase water line size, septic system, add oil/sand separator, hvac system, electrical distribution, domestic plumbing fixtures, interior doors, exterior doors, exterior concrete, and interior concrete.
Bismarck Storage Building	Storage Building	Bismarck	1976		12,200	\$150,000						Roof replacement.
Center Storage Building	Storage Building	Bismarck	1976		3,712	\$100,000						Replace with new storage building at site of new section building.
Center Storage Shed	Storage Building	Bismarck	2001		640	\$20,000						Move to new section yard



	T	1	1								Т	
Facility	Facility Type	District/Division	Year Built/Updated /Acquired	Update Bu	uliaing i -	ger & Alarm /	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase 1	Caution Condition Phase 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed
								2	-		Danam ₆	
Center Tractor Shed	Storage Building	Bismarck	2000	640								
Flasher Storage Shed	Storage Building	Bismarck	2001	640								
Glen Ullin Storage Building	Storage Building	Bismarck	1976	2,40								
Glen Ullin Storage Building	Storage Building	Bismarck	1990	1,50								
Glen Ullin Storage Shed	Storage Building	Bismarck	2007	768								
Linton Storage Building	Storage Building	Bismarck Bismarck	1976 1976	2,40 640								
Linton Storage Shed Linton Tractor Shed	Storage Building Storage Building	Bismarck	1997	640								
McClusky Storage Shed	Storage Building	Bismarck	2001	640								
Napoleon Storage Building		Bismarck	1976	2,40								
Napoleon Storage Shed	Storage Building	Bismarck	2001	640								
New Salem Tractor Shed	Storage Building	Bismarck	2000	640)							
Selfridge Storage Shed	Storage Building	Bismarck	2001	640)							
Steele Storage Building 1	Storage Building	Bismarck	1976	2,40	00							
Steele Storage Building 2	Storage Building	Bismarck	1978	2,40								
Steele Storage Shed	Storage Building	Bismarck	2012	768								
Sterling Tractor Shed	Storage Building	Bismarck	1999	1,05	56							
Underwood Storage Shed	Storage Building	Bismarck	1000									
Wilton Tractor Shed	Storage Building	Bismarck Davils Lake	1999	640				¢2.500				Quarhand days an analy system
Cando Storage Shed	Storage Building	Devils Lake	1976	896 2,68		\$12,000		\$2,500				Overhead door opener system. Heating unit replace and undate lighting, new everhead and walk in doors, rede interior (rotten sheet rock, better ventilation.) Missing shingles
Carrington Storage Building	Storage Building	Devils Lake	2007			\$12,000		440.00				Heating unit, replace and update lighting, new overhead and walk-in doors, redo interior (rotten sheet rock, better ventilation.) Missing shingles , replace with steel roof.
Carrington Storage Shed	Storage Building	Devils Lake	2007	1,12				\$40,000	¢EE 000			New roof, steel siding, overhead door, power and lighting, extend apron in front, update lighting. Overhead doors and popular, now lighting, walk in doors, exhaust fan ventilation, replace quick recovery heaters, higher capacity but water.
Devils Lake Equipment Storage Building	Storage Building	Devils Lake	1976	8,40	00				\$55,000			Overhead doors and openers, new lighting, walk-in doors, exhaust fan ventilation, replace quick recovery heaters, higher capacity hot water
Fossandan Staraga Building	Storage Building	Devils Lake							\$50,000			heater, walk-in doors, heat, floor drain system, upgrade lighting. Raise and put on cement, new roof and siding, install overhead door and walk-in door, power and lights.
Fessenden Storage Building Langdon Storage Building	Storage Building	Devils Lake	1976	2,40	00		\$2,000		\$30,000			Replace walk-in door.
Maddock Storage Shed	Storage Building	Devils Lake	2007	1,12			72,000			\$60,000		Wall sheeting, concrete floor, replace siding with steel siding.
Pekin Storage Shed	Storage Building	Devils Lake	2008	1,12					\$40,000	700,000		Lighting system, replace doors with overhead door, replace shingles and vinyl siding with steel.
Rolla Storage Building	Storage Building	Devils Lake	1976	2,40				\$45,000	¥ 12,222			Replace off of the doors, new lighting, replace roof and repair leaks.
Rolla Storage Shed	Storage Building	Devils Lake		,		\$20,000		\$75,000				Move building to different area in yard, set on concrete floor, replace siding and shbingles with steel, add power and lighting, add walk-in door, new overhead door.
Rugby Storage Shed	Storage Building	Devils Lake	1980	896	5	\$10,000			\$70,000			Lift up and set on concrete, replace siding and shingles with steel, improve lighting, add walk-in door, install an overhead door. 5 new liftmaster openers with photo eyes, safety edges & remotes.
Beach North Storage Shed	Storage Building	Dickinson	2001	640)	\$5,000						Roof
Beach South Storage Shed	Storage Building	Dickinson	2003	640)	\$5,000						Roof
Belfield Storage Building	Storage Building	Dickinson	1976	2,40	00	\$19,800	\$19,800	\$19,800	\$19,800	\$19,800		Interior lighting, wall sheeting, electrical system, overhead doors and openers, exterior doors, roof, overhead door framing, gutters, and exterior concrete.
Belfield Storage Shed	Storage Building	Dickinson	2003	640)	\$5,000						
Dickinson Cold Storage Building	Storage Building	Dickinson	2002	2,60	00	\$6,000	\$6,000	\$6,000	\$6,000	\$6,000		Roof, exterior door, security system, add concrete floor, and resheet rusted wall.
Dickinson Storage Shed	Storage Building	Dickinson	1976	1,4	70	\$5,000	\$5,000	\$5,000	\$5,000	\$5,000		Roof, electric power, garage door openors, concrete floor and apron, and overhead door.
Dickinson Warm Storage Building	Storage Building	Dickinson	1976	6,00	00	\$66,200	\$66,200	\$66,200	\$66,200	\$66,200		Interior concrete, interior wall sheeting, electrical system, ventilation system, exterior wall sheeting, roof, sill plate, overhead doors framing, gutters, exterior concrete, sand/oil separator, and lift pump.
Hettinger Storage Shed	Storage Building	Dickinson	2003	640		\$4,000						
Killdeer Storage Shed	Storage Building		2001	640		\$4,000	\$4,000			\$4,000		Roof, overhead door, add electricity, door openers, concrete floor, and sheeting.
Mott Storage Building	Storage Building	Dickinson	1976	2,40		\$7,800	\$7,800	\$7,800	\$7,800	\$7,800		Interior lighting, overhead doors and openers, exterior doors, roof, windows, and exterior concrete.
Richardton Storage Shed	Storage Building	Dickinson	2001	640		\$3,000	\$3,000	\$3,000	\$3,000	\$3,000		Roof, concrete floor, and overhead door.
Casselton Storage Building Casselton Storage Shed	Storage Building	Fargo	1976 1981	1,50 858								
Fargo Storage Building	Storage Building Storage Building	Fargo Fargo	1981	7,77								
Fargo Storage Building Fargo Storage Shed	Storage Building Storage Building	Fargo	2006	816								
Forman Storage Building		Fargo	1976	1,80								
Hillsboro Storage Building		Fargo	1984	2,68								
Hillsboro Storage Shed	Storage Building	Fargo	1984	1,04								
Leonard Storage Building	Storage Building	Fargo	1976	1,50		\$10,000						Roof replacement
Leonard Storage Shed	Storage Building	Fargo	1976	858				\$25,000				Roof replacement.
Lidgerwood Storage Shed	Storage Building	Fargo	1976	858	3							
Lisbon Storage Building	Storage Building	Fargo				\$25,000						Roof replacement
Lisbon Storage Shed	Storage Building	Fargo	2003	1,11				\$25,000				Roof replacement.
Mayville Storage Building	Storage Building	Fargo	2003	1,12								
Mayville Storage Shed	Storage Building	Fargo	1984	858 2,28		\$75,000						Floor Ponlocoment
Wahpeton Storage Building Wyndemere Storage Building	Storage Building	Fargo	1976 1976	858		\$75,000						Floor Replacement.
Adams Storage Shed	Storage Building Storage Building	Fargo Grand Forks	1976	936								
Aneta Storage Building	Storage Building	Grand Forks	1976	2,40								
Cavalier Storage Shed	Storage Building	Grand Forks	1976	864								
Cooperstown Storage Building	Storage Building	Grand Forks	1976	2,68								
Drayton Storage Building			1976	2,40								
Drayton Storage Shed	Storage Building	Grand Forks	1991	1,1								
Grafton Storage Shed	Storage Building		1976	936								



Facility	Facility Type	District/Division	Year Built/Updated /Acquired	Projected Update Biennium	Existing Building (size)	Danger & Alarm Condition	Alert Condition Phase 1	Alert Condition Phase 2	Caution Condition Phase 1	Caution Condition Phase 2	Additional Needed Repairs without New Building	Improvement and Repair Projects Needed
Grand Forks Stake Storage Building	Storage Building	Grand Forks	1976		2,640			40= 000				
Grand Forks Storage Building	Storage Building	Grand Forks	1976		2,200			\$35,000				Re-roof the cutting edge building / garage on north side of truck storage building. Add steel siding to cutting edge building / garage. New overhead door on cutting edge building / garage.
Grand Forks Storage Building	Storage Building	Grand Forks	1976		2,400							7.00
Larimore Storage Building	Storage Building	Grand Forks	1976		2,400							
Michigan Storage Building	Storage Building	Grand Forks	1976		2,400							
Michigan Storage Shed	Storage Building	Grand Forks	2002		1,120							
Bottineau Storage Building	Storage Building	Minot	1976		2,000		\$15,000					roof needs some repairs (sealer and/or panels replaced)
Harvey Storage Building	Storage Building	Minot	1976		2,400							
Harvey Storage Shed	Storage Building	Minot	1976		480				\$15,000			add exterior walk in doors, and overhead door
Kenmare Storage Building	Storage Building	Minot	1976		1,200			\$15,000				add walk in doors and overhead door and opener
Minot Cold Storage Building	Storage Building	Minot	1976		8,204					\$250,000		Build out cold storage.
Minot Storage Building	Storage Building	Minot	1977		6,210							
Mohall Storage Shed	Storage Building	Minot	2005									
Edgeley Storage Building	Storage Building	Valley City	1976		2,400					\$50,000		Replace metal sheeting.
Ellendale Storage Shed	Storage Building	Valley City	1976		1,056					4=0.0		
Medina Storage Building	Storage Building	Valley City	1976		1,952					\$50,000		Replace metal sheeting.
Oriska Storage Shed	Storage Building	Valley City	1976		640	\$20,000	440.000			\$20,000		Install metal sheeting over wood exterior.
Valley City Storage Building	Storage Building	Valley City	1976 1976		8,800	\$30,000	\$40,000	¢20.000				Remove and replace metal roof that is leaking and remove and replace overhead and walk in doors.
Valley City Storage Shed	Storage Building	Valley City	1984		1,089 2,160			\$30,000				Install metal sheeting over wood exterior.
Wishek Storage Building	Storage Building	Valley City	1964		2,100							
Wishek Storage Shed Bowbells Storage Shed	Storage Building Storage Building	Valley City Williston					\$25,000					New 20' x 30' shed.
Crosby Storage Building	Storage Building	Williston	1976			\$15,000	\$25,000					Roof, and remove and replace interior.
Crosby Storage Shed	Storage Building	Williston	1970			\$13,000	\$25,000					New 20' x 30' shed.
New Town Storage Building	Storage Building	Williston	1976		2,400		\$25,000					New 20' x 30' storage shed
Stanley Storage Building	Storage Building	Williston	1976		2,400		\$23,000					new 20 x 30 storage sinca
Stanley Storage Shed	Storage Building	Williston	1976		640		\$25,000					New 20' x 30' shed.
Watford City Storage Building	Storage Building	Williston	1976		2,400	\$25,000						Roof, overhead door, heater units, lighting, waterline, bathroom, and waste water removal.
Williston Storage Building	Storage Building	Williston	1976		4,100	\$20,000						Heater units, insulation, lighting, outlets, walk in doors, siding, racks, shelves, work bench, and raise floor.
Williston Storage Shed 1	Storage Building	Williston	1976		,	\$10,000						Doors, roof, siding, electricity, and floor.
Williston Storage Shed 2	Storage Building	Williston				\$12,500						Doors, roof, siding, electricity, floor, fence, shelving, and racks.
Bismarck Truck Barn	Truck Barn	Bismarck	2017	27-29	23,000				\$185,000			Exterior concrete.
Devils Lake Truck Barn	Truck Barn	Devils Lake	2002		8,800		\$185,000		\$105,000	\$88,950		Exterior concrete, interior concrete, oil/sand separator, hot water pumps, lighting, exhaust fan ventilation, replace quick recovery heaters, hot water heater, backflow detector, and overhead doors. Potentially add automatic truck wash system to the building that would include remodeling of the existing building and an addition.
Dickinson Truck Barn	Truck Barn	Dickinson	NA	25-27								
Fargo Truck Barn	Truck Barn	Fargo	2013	27-29	18,000							
Grand Forks Truck Barn	Truck Barn	Grand Forks	2003	29-31	9,600	\$10,000			\$107,500	\$66,200		Exterior doors, overhead doors and openers, and door fobs.
Minot Truck Barn	Truck Barn	Minot	2006	25-27	9,600			\$7,500				Replace ceiling exhaust fans/motors.
Jamestown Truck Barn	Truck Barn	Valley City	2003	29-31	8,800	\$65,000	\$10,000	\$10,000	\$255,050	\$230,000		Concrete floor drains, connect to city sewer system, parking lot improvements, and overlay hot bit pvmt.
Valley City Truck Barn	Truck Barn	Valley City	2015		17,000				\$40,000	\$307,550		Improve storm water runoff system, overhead doors, plumbing fixtures, add walk in door in NW corner, and exterior doors.
Williston Truck Barn	Truck Barn	Williston	2019	23-25	18,000	\$130,000						Heated wash bay outdoor concrete slab, walk in doors to shop, and bay extension.
Devils Lake Truck Barn 2	Truck Barn	Devils Lake	NA	25-27								Build one.
Beach Weigh Station	Weigh Station	Dickinson										
Bowman Weigh Station	Weigh Station	Dickinson										
Devils Lake Weigh Station	Weigh Station	Devils Lake							420.000			No fee less and less a
Mooreton Weigh Station	Weigh Station	Fargo		27.20					\$30,000		620,000	New fencing around lagoon.
West Fargo Weigh Station	Weigh Station	Fargo		27-29							\$30,000	New fencing around lagoon.
Grand Forks Weigh Station	Weigh Station	Grand Forks		20.21							¢100.000	Damous without probably provinces and province
Joliette Weigh Station Minot Weigh Station	Weigh Station	Grand Forks Minot	2003	29-31	80						\$100,000	Remove rutted asphalt pavement and repave.
Panger Weigh Station	Weigh Station	Williston		25-27	80							
ranger weigh station	Weigh Station	WIIIISLOII		23-21								



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
DOT - Bismarck Shop	Energy Management and DDC-Base Scope	The control system is from 2000 as is most of the equipment and sequences. Over time, this equipment becomes out of calibration and programming can be optimized with new strategies.	Condition Alert	4.4	\$1,235	\$190	\$1,425	\$40,500	Payback 19.7	Remaining	Remaining \$0	Remaining
DOT - Bismarck Shop	Energy Management and DDC-Enhanced Scope	Same as C.1a.	Alert	4.2	\$1,235	\$190	\$1,425	\$96,500	34.3		\$0	
DOT - Bismarck Shop	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting technology, including bulbs and ballasts.	Alert	4.3	\$985	\$200	\$1,185	\$39,500	22.0		\$0	
DOT - Bismarck Shop	Lighting Retrofit - Enhanced Project	Same as E.1a.	Alert	4.3	\$995	\$200	\$1,195	\$47,500	24.8		\$0	
,	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed around windows, exterior doors, and wall/roof junctions, which allows cold air to infiltrate into the buildings.	Caution	2.7	\$895	\$0	\$895	\$41,750	27.5			\$41,750
DOT - Bismarck Shop	Roof Replacement	The existing EPDM membrane roof is from 2005 with small leaks through the years. These systems should be planned for future replacement.	Caution	2.2	\$0	\$0	\$0	\$570,000				\$570,000
DOT - Bismarck Shop	Exterior Door Replacement	Exterior doors around the facility are showing wear and tear. These systems should be planned for future replacement.	Acceptable	1.6	\$0	\$0	\$0	\$113,500				
DOT - Bismarck Shop	Window Replacement	The window systems are original from 1978 and beyond their life expectancy. These systems should be planned for future replacement.	Alert	2.7	\$55	\$0	\$55	\$163,000			\$163,000	
DOT - Bismarck Shop	Install Fire Suppression System	The district staff identified this project that they would like added to their project list.	Caution	2.6	\$0	\$0	\$0	\$168,000				\$168,000
DOT - Bismarck Shop	Boiler Replacement	The Weil McClain hot water boilers are original from 1978, serving the shop in-floor heat and past the end of their life expectancy.	Alert	2.9	\$45	\$0	\$45	\$124,000			\$124,000	
DOT - Bismarck Shop	Domestic Hot Water Heater Replacement	The domestic water heater in the facility was installed in 2019.	Acceptable	1.7	\$0	\$0	\$0	\$6,200				
DOT - Bismarck Shop	Unit Ventilator Replacement	The unit ventilators that serve the west shop are original from 1976 and gas fired.	Alert	3.1	\$0	\$0	\$0	\$22,250			\$11,125	
DOT - Bismarck Shop	Infrared Heater Replacement	The infrared unit heaters that serve the west shop are original from 1976.	Alert	2.7	\$0	\$0	\$0	\$34,000			\$34,000	
Bismarck Material & Research	Energy Management and DDC - Base Scope	The control system is from 2007 as is most of the equipment and sequences. Over time, this equipment becomes out of calibration and programming can be optimized with new strategies.	Alert	4.4	\$1,590	\$240	\$1,830	\$30,750	13.3		\$0	
Bismarck Material & Research	Energy Management and DDC - Enhance Scope	Same as C.2a.	Alert	3.9	\$1,745	\$270	\$2,015	\$283,000			\$0	
Bismarck Material & Research	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting technology, including bulbs and ballasts.	Alert	4.5	\$4,485	\$900	\$5,385	\$48,000	7.8		\$0	



Facility	Short Description		Asset Condition	Priority	Utility Savings	O&M Savings	Total Savings	Net Cost	Simple Payback	Alarm Condition Remaining	Alert Condition Remaining	Caution Condition Remaining
Bismarck Material & Research	Lighting Retrofit - Enhanced Project	Same as E.2a.	Alert	4.5	\$4,535	\$910	\$5,445	\$54,250	8.6	rtemanning	\$0	rtemanning
Bismarck Material & Research	Electrical Distribution System Replacement	The electrical distribution is estimated to be from 1976 in the original part of the building and 1991 in the west side addition. These systems should be planned for upgrading.	Alert	3.5	\$0	\$0	\$0	\$175,000			\$0	
Bismarck Material & Research	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed around windows, exterior doors, and wall/roof junctions, which allows cold air to infiltrate into the buildings.	Caution	2.6	\$620	\$0	\$620	\$34,750	30.7			\$0
Bismarck Material & Research	Window Replacement	There are window systems from 1974 making these windows well beyond their life expectancy. These systems should be planned for future replacement.	Alarm	3.4	\$90	\$0	\$90	\$74,000		\$0		
Bismarck Material & Research	Exterior Door and Garage Door Replacement	Exterior and garage doors around the facility are showing wear and tear such as paint fading. These systems should be planned for future replacement.	Alarm	3.2	\$0	\$0	\$0	\$50,250		\$0		
Bismarck Material & Research	Asbestos Floor Tile Replacement	There is a lot of asbestos floor tile 1974 that is beyond its life expectancy and a replacement plan should be put in place. It is recommended to remove all asbestos containing materials (ACM's) in the facilities.	Alarm	3.1	\$0	\$0	\$0	\$304,000		\$0		
Bismarck Material & Research	Boiler Replacement	The Multi-Temp hot water boilers are original from 1974 and beyond their life expectancy.	Alert	2.9	\$115	\$0	\$115	\$370,000			\$0	
Bismarck Material & Research	Hot Water Piping Replacement	The hot water distribution piping is original from 1974 and approaching the end of its life expectancy.	Alert	2.7	\$0	\$0	\$0	\$306,000			\$0	
Bismarck Material & Research	VAV Replacement	The variable air volume (VAV) boxes serving the offices and labs are original from 1974. Unless there has been a cleaning program, these boxes are likely dirty reducing their efficiency.	Alert	3.1	\$0	\$0	\$0	\$285,000			\$0	
Bismarck Material & Research	Domestic Water Fixture Efficiency Improvements	The domestic water fixtures in the facility are various ages. There are opportunities to reduce water flow of the fixtures.	Caution	2.4	\$55	\$10	\$65	\$4,800	36.0			\$0
Bismarck Material & Research	MAU Replacement	The make up air handling unit that serves the boiler room is beyond its life expectancy.	Alarm	3.7	-\$110	\$0	-\$110	\$62,000		\$0		
Bismarck Material & Research	AHU-1 and 2 replacement	The variable volume air handling units are original to the building from 1974. These units should be replaced and resized based on the loads and spaces served by the air handling units.	Alarm	3.7	-\$770	\$0	-\$770	\$279,000		\$0		
Bismarck Material & Research	Fume Hood Replacement	The laboratory areas have fume hoods that appear to be from 1974. These units should be looked at for replacement due to the large amount of air that is removed from the space by these hoods.	Alert	3.1	\$0	\$0	\$0	\$134,000			\$0	
Bismarck District Office	Life Between Floors	The district staff identified this project that they would like added to their project list.	Caution	3.0	\$0	\$0	\$0	\$62,000				\$62,000
Bismarck District Office	Energy Management and DDC - Base Scope	The control system is from 2005 as is most of the equipment and sequences. Staff commented on issues with heating being inconsistent through the building. Over time, this equipment becomes out of calibration and programming can be optimized with new strategies.	Alert	4.2	\$455	\$70	\$525	\$43,750	38.5		\$0	



Facility	Short Description		Asset Condition	Priority	Utility Savings	O&M Savings	Total Savings	Net Cost	Simple Payback	Alarm Condition Remaining	Alert Condition Remaining	Caution Condition Remaining
		Same as C.3a.	Alert		Javings	Savings	Surings		rayback	Remaining	\$0	Remaining
Bismarck District					4.0=	400	ÅE.CE	6400 500			Ψŏ	
Office	Energy Management and DDC - Enhance Scope			3.9	\$485	\$80	\$565	\$108,500				
Bismarck District		A majority of the building utilizes fluorescent lighting		4.4	\$775	\$160	\$935	\$16,750	14.0		\$0	
Office	Lighting Retrofit - Base Project	technology, including bulbs and ballasts.	Alert		7	1	7000	7-0,100			ΨŪ	
Bismarck District	Lighting Retrofit - Enhanced Project	Same as E.4a.	Alert	4.4	\$785	\$160	\$945	\$20,000	15.9		\$0	
Office			7		ψ, σσ	7200	φσ .σ	420,000			ÇÜ	
Office												
Bismarck District	Parking Lot Lighting	The district staff identified this project that they would like	Caution	2.1	\$0	\$0	\$0	\$118,000				\$118,000
Office	Tarking Lot Lighting	added to their project list.	Caution	2.1	70	٦٥	70	7110,000				Ş110,000
Bismarck District	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed	Alert	3.2	\$60	\$0	\$60	\$3,150	29.6		\$3,150	
Office	Sear Building Envelope to Williamize All Leakage	around windows, exterior doors, and	Aleit	3.2	Ş00	50	500	75,150	25.0		\$5,150	
Office												
		wall/roof junctions, which allows cold air to infiltrate into the								ć02.000		
Bismarck District		The existing ballasted EPDM membrane roof appears to be								\$82,000		
	Roofing Replacement	from 1988 with small leaks through the years. These systems	Alarm	3.2	\$35	\$0	\$35	\$82,000				
Office		should be planned for future replacement.										
					40-	4.0	4	4000.000				
Bismarck District	Window Replacement	There are window systems from 1988 around the facility	Alert	2.7	\$25	\$0	\$25	\$303,000			\$303,000	
Office		along with leaking and draft issues. These										
		systems should be planned for future replacement.										
Bismarck District	Exterior Door Replacement	Exterior doors around the facility are showing wear and tear.	Alarm	3.2	\$0	\$0	\$0	\$11,300		\$11,300		
Office		These systems should be planned for										
		future replacement.										
Bismarck District	District Brick Update	The district staff identified this project that they would like	Alert	2.9	\$0	\$0	\$0	\$92,500			\$92,500	
Office		added to their project list.										
Bismarck District	Envelope Insulation	The district staff identified this project that they would like	Alert	2.9	\$0	\$0	\$0	\$185,000			\$185,000	
Office		added to their project list.										
Bismarck District	Yard Landscaping	The district staff identified this project that they would like	Caution	2.9	\$0	\$0	\$0	\$31,000				\$31,000
Office		added to their project list.										, - ,
Bismarck District	Security Fence Repairs	The district staff identified this project that they would like	Caution	2.9	\$0	\$0	\$0	\$24,750				\$24,750
Office		added to their project list.			, -		, -	' ' '				Ψ= .,,, σσ
Bismarck District	Asbestos Abatement Allowance	The district staff identified this project that they would like	Alert	2.9	\$0	\$0	\$0	\$154,000			\$154,000	
Office		added to their project list.			7.5	, , ,	7 -	, , , , , , , , , , , , , , , , , , , ,			ψ13 1,000	
Bismarck District	Tile Floor Replacement	There is a lot of vinyl tile from 2015 that is nearing the end of	Acceptable	1.5	\$0	\$0	\$0	\$27,500				
Office	The Free Heptasement	its life expectancy. Flooring has a low	, 1000p table		4.0	4.5	70	427,555				
Office		life expectancy, and a replacement plan should be put in										
		place for each flooring system.										
Bismarck District	First Floor Ceiling Replacement	The acoustical ceiling tile throughout the building appears to	Alert	2.6	\$0	\$0	\$0	\$18,250			Ć10.2F0	
	First Floor Celling Replacement		Alert	2.0	ŞU	ŞU	3 0	\$10,250			\$18,250	
Office		be from 2007 with areas that are										
		stained has reached its life expectancy. A replacement plan										
		should be in place for ceiling systems.										
Bismarck District	Second Floor Ceiling Replacement	The textured ceiling on the second floor appears to be	Alarm	3.1	\$0	\$0	\$0	\$23,000		\$23,000		
Office		original from 1957 and has exceeded its life										
		expectancy. A replacement plan should be in place for ceiling	1									
		systems.										
Bismarck District	Textured Ceiling Replacement	The district staff identified this project that they would like	Alarm	3.1	\$0	\$0	\$0	\$12,500		\$12,500		
Office	<u> </u>	added to their project list.				'		. ,====		,,-		
Bismarck District	Boiler Replacement	The Slant Fin hot water boilers are new from 2012 and have	Acceptable	1.9	\$20	\$0	\$20	\$197,000				
Office		lot of life expectancy left.						+ =5.,500				
Jilice		lot of the expectancy left.										
Bismarck District	Hot Water Pipe Replacement	The hot water distribution piping to the radiation is original	Alert	2.7	\$0	\$0	\$0	\$108,500			\$108,500	
Office		from 1957 and has exceeded its life										
		expectancy.				Ī	Ī	Ī	I			



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
<u>-</u>			Condition	Í	Savings	Savings	Savings		Payback	Remaining	Remaining	Remaining
Bismarck District Office	Domestic Hot Water Heater Replacement	The domestic water heater in the facility appears to be from 2007.	Alert	2.7	\$0	\$0	\$0	\$6,200			\$6,200	
Bismarck District Office	Upgrade Plumbing Systems	The district staff identified this project that they would like added to their project list.	Alert	3.5	\$0	\$0	\$0	\$24,750			\$24,750	
Bismarck District Office	Addition for Construction & Storage	The district staff identified this project that they would like added to their project list.		2.6	\$0	\$0	\$0	\$616,000				
Bismarck District Office	New Building (8000 sq ft)	The district staff identified this project that they would like added to their project list.		2.6	\$0	\$0	\$0	\$3,090,000				
Bismarck District Office	New Building (12000 sq ft)	The district staff identified this project that they would like added to their project list.		2.6	\$0	\$0	\$0	\$4,550,000				
Bismarck District Office	Women's Restroom	The district staff identified this project that they would like added to their project list.	Caution	2.6	\$0	\$0	\$0	\$49,250				\$49,250
Bismarck District Office	AHU-1 Replacement	The air handling units was installed in 1980 and has exceeded its life expectancy. This unit is used only in the summer for cooling and fresh air in the building, but it does not operate or provide ventilation in the winter. This unit should be replaced and resized based on the loads and spaces spread by the air handling unit.	Alarm	3.7	-\$15	\$0	-\$15	\$74,000		\$74,000		
Central Office - Bismarck	Energy Management and DDC-Base Scope	The control system is from 2015 as is most of the equipment and sequences. Over time, this equipment becomes out of calibration and programming can be optimized with new strategies.	Acceptabl e	3.2	\$3,000	\$450	\$3,450	\$168,000	28.2			
Central Office - Bismarck	Energy Management and DDC-Enhanced Scope	Same as C.4a.	Acceptabl e	2.8	\$3,000	\$450	\$3,450	\$406,000				
Central Office - Bismarck	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting technology, including bulbs and ballasts.	Alert	4.5	\$13,780	\$2,760	\$16,540	\$188,000	9.6		\$0	
Central Office - Bismarck	Lighting Retrofit - Enhanced Project	Same as E.5a.	Alert	4.4	\$13,925	\$2,790	\$16,715	\$219,000	10.9		\$0	
Central Office - Bismarck	Electrical Switchgear Replacement	The electrical switchgear in the basement mechanical room is estimated to be from 1967. This system should be planned for upgrading.	Alert	3.5	\$0	\$0	\$0	\$363,000			\$363,000	
Central Office - Bismarck	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed around windows, exterior doors, and wall/roof junctions, which allows cold air to infiltrate into the buildings.		2.7	\$310	\$0	\$310	\$16,000	29.2			\$16,000
Central Office - Bismarck	Window Replacement	The window systems are original to the building from 1967 and single pane, which causes comfort complaints. These systems should be planned for future replacement.	Alarm	3.2	\$455	\$0	\$455	\$650,000		\$650,000		
Central Office - Bismarck	Carpet Replacement	Carpet tile was installed during the remodels in 2015 and are beginning to show wear in the high traffic areas. Flooring has a low life expectancy, and a replacement plan should be put in place for each flooring system.	Acceptabl e	1.5	\$0	\$0	\$0	\$707,000				
Central Office - Bismarck	Kewanee Boiler Replacement	The Kewanee hot water boiler is original from 1967 and has exceeded its life expectancy.	Acceptabl e	4.2	\$115	\$0	\$115	\$0				
Central Office - Bismarck	Complete Boiler Replacement	In addition to the Kewanee boiler, the PK Thermific hot water boiler was installed in 1998 and is nearing the end of their life expectancy. Replacement scheduled 2020/2021	Acceptabl e	4.4	\$165	\$0	\$165	\$0				



Facility	Short Description		Asset Condition	Priority	Utility Savings	O&M Savings	Total Savings	Net Cost	Simple Payback	Alarm Condition Remaining	Alert Condition Remaining	Caution Condition Remaining
Central Office - Bismarck	Hot Water Distribution Replacement	The hot water distribution piping to the building is original from 1967 and has exceeded its life expectancy.	Caution	2.6	\$0	\$0	\$0	\$1,510,000	rayback	rtemannig	Temaming	\$0
Central Office - Bismarck	Chiller Replacement	The Trane water cooled chiller is original from 1967 and has exceeded its life expectancy.	Alarm	3.7	\$0	\$0	\$0	\$1,008,000		\$0		
Central Office - Bismarck	Domestic Hot Water Heater Replacement - Improvement no longer needed 8/24/23	There are multiple domestic water heaters in the facility of various ages.	Caution	2.2	\$0	\$0	\$0	\$24,750				\$0
Central Office - Bismarck	Domestic Piping Replacement	The domestic water piping throughout the facility appears original from 1967 and has exceeded its life expectancy.	Alert	2.4	\$0	\$0	\$0	\$629,000			\$0	
Devils Lake District Bldgs	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting technology, including bulbs and ballasts.	Alert	4.2	\$825	\$170	\$995	\$60,250	32.2			
Devils Lake District Bldgs	Lighting Retrofit - Enhanced Project	Same as E.7a.	Alert	3.9	\$830	\$170	\$1,000	\$124,000			\$124,000	
Devils Lake District Bldgs	Electrical Distribution Replacement	The electrical distribution is estimated to be from 1990. This system should be planned for upgrading.	Caution	3.0	\$0	\$0	\$0	\$61,250				\$61,250
Devils Lake District Bldgs	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed around windows, exterior doors, and wall/roof junctions, which allows cold air to infiltrate into the buildings.		3.2	\$200	\$0	\$200	\$7,800	24.5		\$7,800	
Devils Lake District Bldgs	Roof Replacement	The existing roof systems were last replaced in 2008 with small leaks through the years. These systems should be planned for future replacement.	Alert	2.7	\$450	\$0	\$450	\$555,000			\$555,000	
Devils Lake District Bldgs	Surface Parking Lot	The district staff identified this project that they would like added to their project list.	Caution	1.8	\$0	\$0	\$0	\$185,000				\$185,000
Devils Lake District Bldgs	Carpet Replacement	Carpet tile and rolled carpet are of varying ages. Flooring has a low life expectancy, and a replacement plan should be put in place for each flooring system	Acceptabl e	1.5	\$0	\$0	\$0	\$76,000				
Devils Lake District Bldgs	Splined Ceiling Replacement/Repair	The splined ceiling tile throughout the building appears to be from 1976, and has exceeded its life expectancy. A replacement plan should be in place for ceiling systems.		2.6	\$0	\$0	\$0	\$43,500			\$43,500	
Devils Lake District Bldgs	Interior Door Replacement	The interior doors average age through the facility is forty- four (44) years. These interior doors should be planned for future replacement.	Alert	2.6	\$0	\$0	\$0	\$34,000			\$34,000	
Devils Lake District Bldgs	Fire Alarm System Upgrade	The Simplex fire alarm system and devices appear to be from 1988, but the system does not function and is turned off. Fire alarm systems have a low life expectancy, and must be tested regularly to ensure they operate as designed.	Alarm	4.3	\$0	\$0	\$0	\$31,500		\$31,500		
Devils Lake District Bldgs	Install Fire Suppression System - Shop	The district staff identified this project that they would like added to their project list.		2.9	\$0	\$0	\$0	\$117,000				
Devils Lake District Bldgs	Install Fire Suppression System - Shop & Office	The district staff identified this project that they would like added to their project list.	Caution	2.9	\$0	\$0	\$0	\$178,000				\$178,000
Devils Lake District Bldgs	2008 Furnace Replacement	The furnace serving the 2008 lab office addition is original to the addition. This furnace is nearing the end of its life expectancy and should be planned for replacement.	Caution	2.4	\$0	\$0	\$0	\$4,950				\$4,950



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
			Condition	,	Savings	Savings	Savings		Payback	Remaining	Remaining	Remaining
Devils Lake District Bldgs	Domestic Hot Water Heater Replacement	The electric domestic water heater in the facility was installed in 2019.	Acceptabl e	1.7	\$0	\$0	\$0	\$4,350				
Devils Lake District Bldgs	Install Door Access System	The district staff identified this project that they would like added to their project list.		1.9	\$0	\$0	\$0	\$37,000				
Devils Lake District Bldgs	Replace Furnaces with Central Systems	The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces creating temperature control issues.	Caution	2.6	\$0	\$0	\$0	\$829,000				\$829,000
Dickinson District Bldgs	Energy Management and DDC - Base Scope (Dickinson)	The control system is from 2007 as is most of the equipment and sequences. Over time, this equipment becomes out of calibration and programming can be optimized with new strategies	Caution	3.9	\$1,620	\$250	\$1,870	\$37,750	15.3			\$0
Dickinson District Bldgs	Energy Management and DDC - Enhance Scope (Dickinson)	Same as C.5a.	Caution	3.9	\$1,995	\$300	\$2,295	\$52,750	16.9			\$0
Dickinson District Bldgs	Energy Management and DDC - Comprehensive Scope	Same as C.5a.	Caution	3.7	\$1,995	\$300	\$2,295	\$123,500	30.0			\$0
Dickinson District Bldgs	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting technology, including bulbs and ballasts.	Alert	4.4	\$3,845	\$770	\$4,615	\$86,000	14.4		\$0	
Dickinson District Bldgs	Lighting Retrofit - Enhanced Project	Same as E.9a.	Alert	4.4	\$3,885	\$780	\$4,665	\$100,000	16.0		\$0	
Dickinson District Bldgs	Electrical Distribution Replacement	The electrical distribution is estimated to be from 1977. This system should be planned for upgrading.	Alert	3.5	\$0	\$0	\$0	\$230,000			\$230,000	
Dickinson District Bldgs	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed around windows, exterior doors, and wall/roof junctions, which allows cold air to infiltrate into the buildings.		2.7	\$750	\$0	\$750	\$28,000	23.8			\$28,000
Dickinson District Bldgs	Window Replacement	There are window systems from 1977 around the facility. These systems should be planned for future replacement.	Alert	2.8	\$230	\$0	\$230	\$151,000			\$151,000	
Dickinson District Bldgs	Door Replacement	Exterior doors around the facility are showing wear and tear. These systems should be planned for future replacement.	Alarm	3.2	\$0	\$0	\$0	\$77,500		\$77,500		
Dickinson District Bldgs	Redo Parking Lot (Richardton)	The parking lot was poured in 2003 with regular maintenance and crack sealing done over the years to keep the parking lot in good shape.	Alert	2.5	\$0	\$0	\$0	\$197,000				
Dickinson District Bldgs	Resurface Parking Lot (Dickinson)	The parking lot is estimated to be from 2005 with regular maintenance and crack sealing done over the years to keep the parking lot in good shape.	Alert	2.5	\$0	\$0	\$0	\$164,000				
Dickinson District Bldgs	Vinyl Tile Flooring Replacement (Richardton)	The vinyl tile is original from 2003 exceeding its life expectancy. Flooring has a low life expectancy, and a replacement plan should be put in place for each	Alert	2.6	\$0	\$0	\$0	\$3,000			\$0	
Dickinson District Bldgs	Install Fire Suppression System - Shop	The district staff identified this project that they would like added to their project list.		1.7	\$0	\$0	\$0	\$117,000				
Dickinson District Bldgs	Install Fire Suppression System - Shop & Office	The district staff identified this project that they would like added to their project list.	Caution	1.7	\$0	\$0	\$0	\$167,000				\$167,000
Dickinson District Bldgs	Domestic Water Heater Replacement (Mott)	The domestic water heater was installed in 2004.	Alert	2.7	\$0	\$0	\$0	\$3,100				



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
•			Condition		Savings	Savings	Savings		Payback	Remaining	Remaining	Remaining
Dickinson District	Gas Infrared Heat Replacement (Richardton)	The gas infrared heater in the shop area was installed in 2003	Caution	2.2	\$0	\$0	\$0	\$24,750				\$0
Bldgs		and is nearing the end of its life										
		expectancy.	0	2.2	40	40	40	45.000				4.5
Dickinson District	Electric Baseboard Heat (Richardton)	The electric baseboard heat that heats the office area was	Caution	2.2	\$0	\$0	\$0	\$5,200				\$0
Bldgs	0 11 0 1 1 1 1 1	installed in 2003.	A 1	5 0	44.222	4200	44.600	40		4.0		
Dickinson District	Boiler Replacement (Dickinson)	The Multi-Temp hot water boilers are original from 1977 and	Alarm	5.0	\$1,300	\$300	\$1,600	\$0		\$0		
Bldgs		have exceeded heir life expectancy.										
		These boilers serve the heat pump loop and domestic water.										
Dickinson District	Heat Pump Loop Heat Injection Valve	This valve appears to be original from 1977 and has exceeded	Alert	3.7	\$0	\$0	\$0	\$5,950			\$0	
		· · · · · · · · · · · · · · · · · · ·	Aleit	3.7	ŞÜ	Ş0	٥٦	\$3,930			ŞU	
Bldgs	Replacement (Dickinson)	its life expectancy.										
Dickinson District	Building Hot Water Pump Replacement	The hot water pumps serving the heat pump loop distribution	Alert	3.7	\$0	\$0	\$0	\$22,750			\$0	
	(Dickinson)	through the facility are original from	Aicit	3.7	γo	٦٥	٦٥	722,730			ŞU	
Bldgs	(DICKITISOTI)	1977 and have exceeded their life expectancy.										
Dickinson District	Heat Pump Loop Pump Replacement (Dickinson)	The heat pump loop pumps serving the heat pump loop	Alert	3.7	\$0	\$0	\$0	\$22,750			\$0	
	Heat Fullip Loop Fullip Replacement (Dickinson)		Alert	3.7	ŞU	ŞU	٥٦	\$22,730			ŞU	
Bldgs		distribution through the facility are original										
Dickinson District	Cooling Towns Install (Diskinson)	from 1977 and have exceeded their life expectancy.	A la mas	F 0	ćo	6250	¢250	ćo		40		
	Cooling Tower Install (Dickinson)	The cooling tower serving the heat pump loop distribution in	Alarm	5.0	\$0	\$250	\$250	\$0		\$0		
Bldgs		the facility is from 1977 and beyond its		2.4	40	40	40	4440.000			4	
Dickinson District	Hard Borre Bardan and (Birlings)	A majority of the heat pumps that serve the facility are from	Alexan	3.4	\$0	\$0	\$0	\$149,000			\$149,000	
Bldgs	Heat Pump Replacement (Dickinson)	2001, but the staff has started to see	Alert									
		failures recently. Now that the heat pumps have reached										
Dickinson District	Domestic Water Heater Replacement (Hettinger)	The domestic water heater was installed in 2009.	Caution	2.2	\$0	\$0	\$0	\$6,200				\$0
Bldgs												
							<u> </u>					
Dickinson District	Domestic Water Fixture Efficiency Improvements	The domestic water fixtures in the facility are various ages.	Caution	2.6	\$265	\$30	\$295	\$5,050	13.5			\$5,050
Bldgs		There is potential for reducing the water										
		flow to fixtures to achieve energy savings.										
		The control system is from 2007 as is most of the equipment										\$0
Fargo District Building	Energy Management and DDC-Base Scope	and sequences. Over time, this equipment becomes out of	Caution	3.9	\$2,255	\$340	\$2,595	\$39,000	12.1			
80 = 1011100 = 4114110	, Liver By management and DD o Date deepe	calibration and programming can be optimized with new	Saution.	0.5	4 2,233	φσ.σ	1 -,	700,000				
		strategies.					1					
Fargo District Building	Energy Management and DDC-Enhanced Scope	Same as C.6a.	Caution	3.8	\$2,255	\$340	\$2,595	\$109,500	25.8			\$0
Fargo District Building	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting	Alert	4.4	\$2,985	\$600	\$3,585	\$60,500	13.3			
		technology, including bulbs and ballasts.					1					
Fargo District Building	Lighting Retrofit - Enhanced Project	Same as E.11a.	Alert	4.4	\$3,015	\$610	\$3,625	\$70,750	14.9		\$0	
					4	4	4-	4		4.5		
Fargo District Building	Shop Electrical Upgrades	The district staff identified this project that they would like	Alarm	4.3	\$0	\$0	\$0	\$237,000		\$0		
		added to their project list.			4000	4.0	4000	40.4-00				4
Fargo District Building	Seal Building Envelope to Minimize Air Leakage	There are building envelope issues that need to be addressed	Caution	2.8	\$900	\$0	\$900	\$24,500	19.1			\$24,500
		around windows, exterior doors, and										
		wall/roof iunctions. which allows cold air to infiltrate into the			4		4	4				
Fargo District Building	Window Replacement	There are window systems from 1968 on the first floor and	Alarm	3.4	\$205	\$0	\$205	\$51,000		\$0		
		basement that are single pane. These										
		systems should be planned for future replacement.					1					
Fargo District Building	Door Replacement	Exterior doors around the facility are showing wear and tear.	Alert	2.7	\$0	\$0	\$0	\$97,500			\$73,125	
		These systems should be planned for										
		future replacement.										
Fargo District Building	Resurface Parking Lot	The parking lot is from 2007 with regular maintenance and	Alert	2.5	\$0	\$0	\$0	\$576,000			\$576,000	
		crack sealing done over the years to keep										



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
	•	Dallad asynch was installed in 2012 in the office area and is	Condition		Savings	Savings	Savings		Payback	Remaining	Remaining	Remaining
		Rolled carpet was installed in 2013 in the office area and is										\$116,500
Fargo District Building	Carpet Replacement	beginning to show wear in the high traffic areas. Flooring has	Caution	2.1	\$0	\$0	\$0	\$116,500				
		a low life expectancy, and a replacement plan should be put										
		in place for each There is vinyl tile from 2007 in the hallways that is nearing									\$49,000	
Fargo District Building	Vinyl Tile Flooring Replacement	the end of its life expectancy. Flooring has a low life	Alert	2.6	\$0	\$0	\$0	\$49,000			\$49,000	
rango District Danamig	The Flooring Replacement	expectancy, and a replacement plan should be put in place	Allere	2.0	Şΰ	70	70	\$ 13,000				
Fargo District Building	Fire Alarm System Upgrade	The Simplex fire alarm system and devices appear to be from	Alarm	4.3	\$0	\$0	\$0	\$94,000		\$0		
	The riam system spanae	1988. Fire alarm systems have a low	7		γo	, ,	7.5	45 1,000		ΨÜ		
		life expectancy, and must be tested regularly to ensure they										
Fargo District Building	Install Fire Suppression System - Shop	The district staff identified this project that they would like		2.9	\$0	\$0	\$0	\$117,000				
· ·		added to their project list.			·							
Fargo District Building	Install Fire Suppression System - Shop & Office	The district staff identified this project that they would like	Caution	2.9	\$0	\$0	\$0	\$173,000				\$173,000
		added to their project list.										. ,
Fargo District Building	Hot Water Piping Replacement	The hot water distribution piping to the building is original	Alert	2.7	\$0	\$0	\$0	\$388,000			\$388,000	
		from 1968 and has exceeded its life										
		expectancy.										
		The variable air volume (VAV) boxes throughout the facility			\$0	\$0	\$0	\$98,500			\$73,875	
Fargo District Building	VAV Replacement	serving the office areas are original from 1996. Unless there	Alert	3.1								
raigo District Dallallig	NAV Replacement	has been a cleaning program, these boxes are likely dirty	Aicit	5.1								
		reducing their efficiency.										
Fargo District Building	Domestic Hot Water Heater Replacement	There are multiple domestic water heaters in the facility of	Acceptable	1.7	\$0	\$0	\$0	\$12,500				
		various ages.										
Fargo District Building	Furnace Replacement	The Trane furnace serving the shop office was installed in	Caution	2.6	\$0	\$0	\$0	\$9,900				\$9,900
		2007 and is nearing the end of its life										
		expectancy.			4.0-	4-0	4	4				
Fargo District Building	Domestic Water Fixture Efficiency Improvements	The domestic water fixtures in the facility are various ages.	Acceptable	2.1	\$425	\$50	\$475	\$5,700	10.1			
		There are opportunities to reduce water										
Farma District Building	ALIII Dania sanart	flow of the fixtures.	A I =t	2.1	6270	ćo	6270	¢126.000			¢426.000	
Fargo District Building	AHU Replacement	The Trane variable volume air handling unit was installed in	Alert	3.1	-\$370	\$0	-\$370	\$136,000			\$136,000	
		1996. This unit should be replaced and										
		resized based on the loads and spaces served by the air										
		handling units. The make up air handling units that serve the shop have									\$98,500	
		exceeded their life expectancy. A replacement plan should									\$36,300	
Fargo District Building	MALI Renlacement	be in place for future replacement and these units should be	Alert	3.1	-\$375	\$0	-\$375	\$98,500				
	I i i i i i i i i i i i i i i i i i i i	sized properly	7	5.2	φσ.σ	, ,	70.0	700,000				
		for the loads in the spaces they serve										
		The control system is from 2017 as is most of the equipment										
Grand Forks District	Second Management and DDC David Country	and sequences. Over time, this equipment becomes out of		2.4	64.245	6200	Ć4 F4F	¢22.500	46.4			
Bldgs	Energy Management and DDC-Base Scope	calibration and programming can be optimized with new	Acceptable	3.4	\$1,315	\$200	\$1,515	\$33,500	16.4			
-		strategies.										
Grand Forks District	Energy Management and DDC-Enhanced Scope	Same as C.7a.	Acceptable	3.2	\$1,315	\$200	\$1,515	\$129,500	39.0			
Bldgs												
Grand Forks District	Lighting Retrofit - Base Project	A majority of the building utilizes fluorescent lighting	Alert	4.4	\$2,605	\$530	\$3,135	\$42,750	11.2		\$0	
Bldgs		technology, including bulbs and ballasts.					<u> </u>	<u> </u>				
Grand Forks District	Lighting Retrofit - Enhanced Project	Same as E.12a.	Alert	4.4	\$2,635	\$530	\$3,165	\$45,750	11.8		\$0	
Bldgs												
	E				4.5	4.5	4.5	40.00.00			40.55	
Grand Forks District	Electrical Switchgear and Distribution	The electrical switchgear (1997) and distribution (1972) are	Alert	3.5	\$0	\$0	\$0	\$368,000			\$368,000	
Bldgs	Replacement	nearing the end of the life expectancy for										
	<u> </u>	each system. These systems should be planned for										



Encility	Short Description		Asset	Driceity	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
Facility	Short Description		Condition	Priority	Savings	Savings	Savings		Payback	Remaining	Remaining	Remaining
Grand Forks District		The existing ballasted EPDM membrane roof was installed in		2.7	\$320	\$0	\$320	\$862,000			\$862,000	
Bldgs	Roof Replacement	1996 and has experienced with small	Alert									
	·	leaks through the years around the roof drains. These										
Grand Forks District	Window Replacement	systems should be planned for future replacement. There are window systems from 1988 around the facility	Alarm	3.2	\$220	\$0	\$220	\$274,000		¢27.400		
	Willdow Replacement	·	AldIII	3.2	\$220	ŞU	\$220	\$274,000		\$27,400		
Bldgs		along with flashing issues windows around the facility. These systems should be planned for future										
Grand Forks District	Door and Garage Door Replacement	Exterior and garage doors around the facility are showing	Alert	2.7	\$0	\$0	\$0	\$235,000			\$235,000	
Bldgs	l and carage book nephasement	wear and tear such as paint fading. These	7	=17	γ°	4.5	70	Ψ=00,000			7233,000	
2.0.80		systems should be planned for future replacement.										
Grand Forks District	Resurface Parking Lot - East Public Lot	The parking lot was last resurfaced in 2003 with regular	Alert	2.5	\$0	\$0	\$0	\$500,000			\$500,000	
Bldgs		maintenance and crack sealing done over the										
Grand Forks District	Resurface Parking Lot - Rest of Parking Lot	The parking lot was last resurfaced in 2003 with regular	Alert	2.5	\$0	\$0	\$0	\$247,000			\$247,000	
Bldgs		maintenance and crack sealing done over the										
Grand Forks District	Vinyl Tile Flooring Replacement (Grand Forks	There is vinyl tile from 1996 in the restrooms that has			4.0	4.0	40	400.050			\$22,250	
Bldgs	Shop)	exceeded its life expectancy. Flooring has a low life	Alert	2.6	\$0	\$0	\$0	\$22,250				
	<u> </u>	expectancy, and a replacement plan should be put in place										
Grand Forks District	Vinyl Tile Flooring Replacement (Construction	There is vinyl tile from 1991 through a majority of the	Alert	2.6	\$0	\$0	\$0	\$22,250				
Bldgs	Office)	building that has exceeded its life expectancy. Flooring has a low life expectancy, and a replacement plan should be put in	Aleit	2.0	Ų	, JU	٥٦	722,230				
Grand Forks District	Wood Door Replacement (Construction Office)	The wood interior doors were installed in 1991 and are	Alert	2.6	\$0	\$0	\$0	\$7,700				
Bldgs	Wood Boot Replacement (construction office)	approaching the end of their life expectancy.	7 liere	2.0	γo	70	٥٩٥	\$7,700				
Diago		These interior doors should be planned for future										
Grand Forks District	Vinyl Tile Flooring Replacement (Truck Shed)	There is original vinyl tile from 2003 that has exceeded its life	Alert	2.6	\$0	\$0	\$0	\$6,700				
Bldgs		expectancy. Flooring has a low life										
		expectancy, and a replacement plan should be put in place										
Grand Forks District	Vinyl Tile Flooring Replacement (Sign Shop)	There is vinyl tile from 1982 that has exceeded its life	Alert	2.6	\$0	\$0	\$0	\$18,500				
Bldgs		expectancy. Flooring has a low life expectancy,										
		and a replacement plan should be put in place for each		2.2	40	40	40	447.050		40		
Grand Forks District	Domestic Hot Water Heater Replacement	There are multiple domestic water heaters in the facilities of	Alarm	3.3	\$0	\$0	\$0	\$17,250		\$0		
Bldgs		various ages.										
Grand Forks District	Infrared Heater Replacement (Shop)	The infrared heaters in the shop that provide heat were	Caution	2.2	\$0	\$0	\$0	\$25,750				\$25,750
Bldgs	initiated fredeer Replacement (Shop)	installed in 1996.	Caucion	2.2	γū	, ,	٧٠	Ų23,730				¥23,730
21463		mistanea in 1990.										
Grand Forks District	Hanging Heaters Replacement	The hanging heaters in the facilities vary in age, but a	Caution	2.2	\$0	\$0	\$0	\$24,750				\$24,750
Bldgs		majority have exceeded their life expectancy.										
Grand Forks District	Domestic Piping Replacement (Construction	The domestic water piping throughout the facility was	Caution	1.9	\$0	\$0	\$0	\$18,500				
Bldgs	Office)	installed in 1991 and is approaching the end of										
		its life expectancy.										
Grand Forks District	Domestic Piping Replacement (Sign Shop)	The demostic water nining throughout the facility is original	Alert	2.4	\$0	\$0	\$0	\$75,000				
Bldgs	Domestic Piping Replacement (Sign Shop)	The domestic water piping throughout the facility is original from 1974 and has exceeded its life	Alert	2.4	ŞU	ŞU	ŞU	\$75,000				
Diugs												
		expectancy.										
Grand Forks District	Construction Office Remodel	The district staff identified this project that they would like		1.6	\$0	\$0	\$0	\$895,000				
Bldgs		added to their project list.										
Grand Forks District	Construction Office New Building and Demo	The district staff identified this project that they would like		1.6	\$0	\$0	\$0	\$2,780,000				
Bldgs		added to their project list.										
Grand Forks District	RTU Replacement (Grand Forks Office)	The Titan packaged rooftop air handling unit that serves the		3.7	-\$380	\$0	-\$380	\$46,250		\$46,250		
Bldgs		building was installed in 1996 and has										
		exceeded its life expectancy. This unit should be replaced	Alarm									
		with a new rooftop unit that is sized properly for the building.										
	1					<u> </u>						



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition		Caution Condition
,		The second control of the self-time of the transport of	Condition	,	Savings	Savings	Savings	¢5.000	Payback	Remaining	Remaining	Remaining
Grand Forks District	MAU Replacement (Grand Forks Office)	The gas fired make up air handling unit that serves the		3.7	-\$785	\$0	-\$785	\$56,000		\$56,000		
Bldgs		building was installed in 1996 and has										
		exceeded its life expectancy. A replacement make up air	Alarm									
		handling unit should be planned and sized properly for the										
		huilding										
		The gas fired make up air handling unit that serves the			-\$635	\$0	-\$635	\$158,000		\$158,000		
Grand Forks District		building was installed in 1996 and has										
Bldgs	MAU Replacement (Grand Forks Shop)	exceeded its life expectancy. A replacement make up air	Alarm	3.7								
Diags		handling unit should be planned and sized properly for the										
		huilding										
		The make up air handling unit that serves the truck bay was			-\$635	\$0	-\$635	\$29,750		\$29,750		
Grand Forks District		installed in 1974 and has exceeded its life expectancy. A										
	MAU Replacement (Sign Shop)	replacement make up air handling unit should be planned	Alarm	3.7								
Bldgs		and sized properly for										
		the huilding										
		The control system is from 2007 as is most of the equipment										\$0
		and sequences. Over time, this equipment becomes out of			4		4	400				Ψ.
Minot District Bldgs	Energy Management and DDC-Base Scope	calibration and programming can be optimized with new	Caution	3.9	\$1,495	\$230	\$1,725	\$32,750	14.6			
Minot District Bldgs	Energy Management and DDC-Enhanced Scope	strategies. Same as C.8a.	Caution	3.7	\$1,495	\$230	\$1,725	\$94,500	30.3			\$0
Williot District Diags	Energy Management and DDe Enhanced Scope	Sume as clou.	Caation	3.,	71,433	7230	71,723	754,500	30.3			ŞÛ
		A majority of the building utilizes fluorescent lighting									\$0	
Minot District Bldgs	Lighting Retrofit - Base Project	technology, including bulbs and ballasts.	Alert	4.5	\$9,330	\$1,870	\$11,200	\$97,500	7.7		ŞU	
Minot District Bldgs	Lighting Retrofit - Enhanced Project	Same as E.14a.	Alert	4.5	\$9,425	\$1,890	\$11,315	\$106,000	8.2		\$0	
Williot District Blugs	Lighting Retront - Emianced Project	Sallie as E.14a.	Alert	4.5	33,423	\$1,690	\$11,515	\$100,000	0.2		ŞU	
Minot District Bldgs	Electrical Switchgear and Distribution	The electrical switchgear (1961) and distribution (1991) are	Alert	3.5	\$0	\$0	\$0	\$187,000			ć107.000	
Williot District blugs	1		Alert	5.5	ŞU	ŞU	ŞU	\$187,000			\$187,000	
	Replacement	near or exceeding their life expectancy for										
Add at District at District	Dest Destar and	each system. These systems should be planned for	Continu	2.2	¢265	Ć0.	6265	¢464.000				4464.000
Minot District Bldgs	Roof Replacement	The existing EPDM membrane roof was replaced in 2000 with	Caution	2.2	\$265	\$0	\$265	\$461,000				\$461,000
		small leaks through the years. These										
		systems should be planned for future replacement.										
					4.00	4.0	4.00	40-0 000				
Minot District Bldgs	Window Replacement	There are single pane window systems from 1969 around the	Alarm	3.2	\$180	\$0	\$180	\$252,000		\$0		
		facility. These systems should be										
		planned for future replacement.										
Minot District Bldgs	Exterior Door and Overhead Door Replacement	Exterior and garage doors around the facility are showing	Alert	2.7	\$0	\$0	\$0	\$56,000			\$14,000	
		wear and tear such as paint fading. These										
		systems should be planned for future replacement.										
Minot District Bldgs	Resurface Parking Lot	The parking lot was replaced in 2007 with regular	Alert	2.5	\$0	\$0	\$0	\$569,000			\$569,000	
		maintenance and crack sealing done over the years										
		Rolled carpet was installed in 2000 in office/conference			\$0	\$0	\$0	\$37,250			\$0	
Minot District Bldgs	Carnot Ponlacoment	rooms and is showing wear in the high traffic	Alert	2.6								
Minot District Bldgs	Carpet Replacement	areas. Flooring has a low life expectancy, and a replacement	Alert	2.6								
		plan should be put in place for each flooring system.										
		There is a lot of vinyl tile from 2000 in the			\$0	\$0	\$0	\$5,950		\$5,950		
Minot District Bldgs	Vinyl Tile Flooring Replacement	hallways/restrooms that has exceeded its life expectancy.	Alarm	3.1						, , , , ,		
· ·		Flooring has a low life expectancy, and a replacement plan										
Minot District Bldgs	Ceiling Grid Replacement	The acoustical ceiling tile throughout the office area appears	Caution	2.1	\$0	\$0	\$0	\$15,500				\$15,500
	.0	to be from 1998, and nearing its life	220000		••			, _5,555				713,300
		expectancy. A replacement plan should be in place for ceiling										
Minot District Bldgs	Adhered Ceiling Repair/Replacement	The adhered ceiling tile through the laboratory space appears	Alarm	3.1	\$0	\$0	\$0	\$5,950		\$5,950		
Millor District Diugs	namerea cening nepair/nepiacement		- Alariii	5.1	٥ڔ	ا ا	٥ڔ	75,550		3 3,330		
		to be from 1969 exceeding its life										
		expectancy. A replacement plan should be in place for ceiling				l]	l	l			



Facility	Short Description		Asset	Priority	Utility	O&M	Total	Net Cost	Simple	Alarm Condition	Alert Condition	Caution Condition
		The weed interior deeper were installed in 1000 and are	Condition	2.1	Savings	Savings	Savings	¢24.000	Payback	Remaining	Remaining	Remaining
Minot District Bldgs	Wood Door Replacement	The wood interior doors were installed in 1998 and are	Caution	2.1	\$0	\$0	\$0	\$31,000				\$31,000
		approaching their life expectancy. These										
Minot District Bldgs	Fire Alexan Cratera Heaveds	interior doors should be planned for future replacement.	Cautian	2.2	ćo	ćo	ćo	670.000				ά 7 0,000
	Fire Alarm System Upgrade	The Altronix fire alarm system and devices appear be from	Caution	3.2	\$0	\$0	\$0	\$78,000				\$78,000
		2007. Fire alarm systems have a low life										
Batha at Disa dat Disi	E contein Control	expectancy, and must be tested regularly to ensure they	Carlina	2.2	ćo.	ćo	Ć0.	¢06 500				477.050
Minot District Bldgs	Expand Fire Suppression System	The district staff identified this project that they would like	Caution	3.2	\$0	\$0	\$0	\$86,500				\$77,850
841	Harawara Birdikatia Bada arasi	added to their project list.	Carlina	2.2	ćo	ćo	Ć0	6445 500				4445.500
Minot District Bldgs	Hot Water Distribution Replacement	The hot water distribution piping to the building is estimated	Caution	2.2	\$0	\$0	\$0	\$115,500				\$115,500
		to be at least fifty (50) years old, which		4 7	40	40	40	604.750				
Minot District Bldgs	Infrared Heater Replacement	The infrared unit heaters that serve the shop were installed	Acceptable	1.7	\$0	\$0	\$0	\$24,750				
		in 2007 and are approaching the end of										
		their life expectancy.			4.0	4.0	4.0	400			4 -	
Minot District Bldgs	Furnace Replacement	The Carrier furnace serving the shop office was installed in	Alert	2.9	\$0	\$0	\$0	\$29,750			\$0	
		2000 and has exceeded its life expectancy.										
Bathway District of Dist	Floatsia Danah aasad Danda aasaa a	The electric beauty and beauty beauty from the control of	A land	2.7	ćo	ćo	40	624.750			624.770	
Minot District Bldgs	Electric Baseboard Replacement	The electric baseboard heat that heats offices and restrooms	Alert	2.7	\$0	\$0	\$0	\$24,750			\$24,750	
ant or pto to pld.	Development of the David of the Control of the Cont	were installing in 2000.	A1	2.7	ćo	ćo	Ć0	Ć4.050			Ć4.050	
Minot District Bldgs	Domestic Hot Water Heater Replacement	There are multiple domestic water heaters in the facility of	Alert	2.7	\$0	\$0	\$0	\$4,950			\$4,950	
		various ages.										
		The Theory of the 10 and 10 an					 			Å0		
		The Tjernlund multizone air handling unit that serves the								\$0		
Min of District Dides	Multipara AllII Danis sarant	office area was installed in 1969 and has exceeded its life	0.15.005	2.7	6155	ćo	Ć1 F F	¢111 000				
Minot District Bldgs	Multizone AHU Replacement	expectancy. A replacement plan should be in place to	Alarm	3.7	-\$155	\$0	-\$155	\$111,000				
		replace this unit with a new										
Min at District Bldgs	Con First All II Broken and	unit properly sized to serve this area		2.7	¢500	ćo	¢500	6430.000		Å O		
Minot District Bldgs	Gas Fired AHU Replacement	The gas fired make up air handling units that serves the shop		3.7	-\$590	\$0	-\$590	\$139,000		\$0		
		was installed in 1969 and has exceeded	0.15.005									
		its life expectancy. A replacement make up air handling unit	Alarm									
		should be planned and sized properly for the building.										
		T										4-
Vallan City District		The control system is from 2008 as is most of the equipment										\$0
Valley City District Bldgs	Energy Management and DDC-Base Scope	and sequences. Over time, this equipment becomes out of	Caution	3.9	\$2,100	\$320	\$2,420	\$33,250	11.3			
		calibration and programming can be optimized with new										
		strategies.	0 11	2.0	60.450	4222	40.400	405.000	24.2			4-
Valley City District	Energy Management and DDC-Enhanced Scope	Same as C.9a.	Caution	3.8	\$2,150	\$330	\$2,480	\$95,000	24.2			\$0
Bldgs												
Will do blots				2.7	40	40	40	4400 000			40	
Valley City District	Electrical Switchgear and Distribution	The electrical switchgear and distribution is original to the	Alert	3.7	\$0	\$0	\$0	\$190,000			\$0	
Bldgs	Replacement	building from 1973. These systems should										
		be planned for upgrading.			6225	ćo	6225	¢206.000		dan can		
Valley City District	Mindow Doubooms	There are window systems from 1973 around the facility with		2.4	\$225	\$0	\$225	\$206,000		\$20,600		
Bldgs	Window Replacement	the glazing deteriorating and asbestos. These systems should	Alarm	3.4								
		be planned for future replacement and asbestos should be		2.2	40	40	40	402.000		A 5 4 7 0 0		
Valley City District	Exterior Door Replacement	Exterior doors around the facility are showing wear and tear.	Alarm	3.2	\$0	\$0	\$0	\$82,000		\$61,500		
Bldgs		These systems should be planned for										
William State	A de color Alexandro de Alexandro	future replacement.	A.I.	2.2	60	60	40	64.40.000		d4.45.000		
Valley City District	Asbestos Abatement Allowance	The district staff identified this project that they would like	Alarm	3.2	\$0	\$0	\$0	\$148,000		\$148,000		
Bldgs	Court Book or and	added to their project list.		2.0	ćo	60	40	642.750			642.770	
Valley City District	Carpet Replacement	Carpet tile (2012) and rolled carpet (2008) are nearing their		2.6	\$0	\$0	\$0	\$13,750			\$13,750	
Bldgs		life expectancy and are beginning to	Alert									
		show wear in the high traffic areas. Flooring has a low life										
		expectancy, and a replacement plan						ļ.,				
Valley City District	Vinyl Tile Flooring Replacement	There is a lot of original vinyl tile from 2005 that is nearing	Alarm	3.1	\$0	\$0	\$0	\$13,250		\$13,250		
Bldgs		the end of its life expectancy. Flooring has										
		a low life expectancy, and a replacement plan should be put										



Valley City District Bldgs Feplace Fu Bldgs Shop MAU Williston District Bldgs Energy Mai	Door Replacement m System Upgrade re Suppression System Replacement Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement por Access System Furnaces with Central Systems	The interior doors appear original to the building from 1973. These interior doors should be planned for future replacement. The Simplex fire alarm system and devices appear to be original to the facility from 1973, is obsolete and doesn't meet code. Fire alarm systems have a low life The district staff identified this project that they would like added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alarm Caution Alert Alarm Alarm Acceptable Alert Alert	2.6 4.3 2.9 2.9 3.3 1.7	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$23,250 \$19,000 \$179,000 \$69,000 \$24,750 \$6,200	Payback	\$0 \$24,750	Remaining \$23,250 \$69,000	\$179,000
Valley City District Bldgs Feeplace Fu Bldgs Williston District Bldgs Energy Ma Williston District Bldgs Energy Ma	m System Upgrade re Suppression System Replacement Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement	These interior doors should be planned for future replacement. The Simplex fire alarm system and devices appear to be original to the facility from 1973, is obsolete and doesn't meet code. Fire alarm systems have a low life The district staff identified this project that they would like added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alarm Caution Alert Alarm Acceptable Alert	4.3 2.9 2.9 3.3 1.7	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	\$19,000 \$179,000 \$69,000 \$24,750 \$6,200				\$179,000
Valley City District Bldgs Feelace Fu Bldgs Williston District Bldgs Energy Mal	Replacement Gas Heater Replacement C Hot Water Heater Replacement C Piping Replacement	The Simplex fire alarm system and devices appear to be original to the facility from 1973, is obsolete and doesn't meet code. Fire alarm systems have a low life The district staff identified this project that they would like added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Caution Alert Alarm Acceptable Alert	2.9 2.9 3.3 1.7	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$179,000 \$69,000 \$24,750 \$6,200			\$69,000	\$179,000
Valley City District Bldgs Feelace Fu Bldgs Williston District Bldgs Energy Mal	Replacement Gas Heater Replacement C Hot Water Heater Replacement C Piping Replacement	original to the facility from 1973, is obsolete and doesn't meet code. Fire alarm systems have a low life The district staff identified this project that they would like added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Caution Alert Alarm Acceptable Alert	2.9 2.9 3.3 1.7	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$179,000 \$69,000 \$24,750 \$6,200			\$69,000	\$179,000
Valley City District Bldgs Feplace Fu Bldgs Williston District Bldgs Energy Mal	Replacement Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement por Access System	and doesn't meet code. Fire alarm systems have a low life The district staff identified this project that they would like added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Caution Alert Alarm Acceptable Alert	2.9 3.3 1.7 2.4	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0	\$69,000 \$24,750 \$6,200		\$24,750	\$69,000	\$179,000
Pldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Energy Mai	Replacement Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement por Access System	The district staff identified this project that they would like added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alarm Acceptable Alert	2.9 3.3 1.7 2.4	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0	\$69,000 \$24,750 \$6,200		\$24,750	\$69,000	\$179,000
Pldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Energy Mai	Replacement Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement por Access System	added to their project list. The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alarm Acceptable Alert	2.9 3.3 1.7 2.4	\$0 \$0 \$0	\$0 \$0 \$0	\$0 \$0 \$0	\$69,000 \$24,750 \$6,200		\$24,750	\$69,000	\$179,000
Valley City District Bldgs Energy Malliston District Bldgs Williston District Bldgs Energy Malliston District Bldgs Energy Malliston District Bldgs	Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement por Access System	The furnaces that serve the office building (2000) and the shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alarm Acceptable Alert	3.3 1.7 2.4	\$0 \$0	\$0 \$0	\$0	\$24,750 \$6,200		\$24,750	\$69,000	
Valley City District Bldgs Energy Malley City District Bldgs Williston District Bldgs Energy Malley City District Bldgs Energy Malley City District Bldgs Energy Malley City District Bldgs	Gas Heater Replacement c Hot Water Heater Replacement c Piping Replacement por Access System	shop office (1998) have exceeded their life expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alarm Acceptable Alert	3.3 1.7 2.4	\$0 \$0	\$0 \$0	\$0	\$24,750 \$6,200		\$24,750	303,000	
Valley City District Bldgs Feeplace Fu Shop MAU Williston District Bldgs Williston District Bldgs Energy Mai	c Hot Water Heater Replacement c Piping Replacement por Access System	expectancy and experience zone control comfort issues. The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Acceptable Alert	2.4	\$0	\$0	\$0	\$6,200		\$24,750		
Valley City District Bldgs Energy Mai	c Hot Water Heater Replacement c Piping Replacement por Access System	The gas unit heaters in the shop area are original from 1973 and have exceeded their life expectancy. A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Acceptable Alert	2.4	\$0	\$0	\$0	\$6,200		\$24,750		
Valley City District Bldgs Energy Mail Williston District Bldgs Energy Mail	c Piping Replacement poor Access System	A replacement plan should be put in place for each water heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert	2.4			·					
Valley City District Bldgs Energy Mail Williston District Bldgs Williston District Energy Mail	c Piping Replacement poor Access System	heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert	2.4			·					
Valley City District Bldgs Energy Mail Williston District Bldgs Energy Mail	c Piping Replacement poor Access System	heater to be replaced with higher efficiency units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert	2.4			·					
Valley City District Bldgs Energy Malliston District Bldgs Williston District Bldgs Energy Malliston District Bldgs	por Access System	units. The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces			\$0	\$0	\$0	624.000				
Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Williston District Bldgs Williston District Bldgs Energy Mar	por Access System	The domestic water piping throughout the facility is original from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces			\$0	\$0	\$0	624.000				
Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Williston District Bldgs Williston District Bldgs Energy Mar	por Access System	from 1973 and has exceeded its life expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces			Ş0	ŞÜ	J U	// [][[][]			¢24.000	
Valley City District Bldgs Valley City District Bldgs Valley City District Bldgs Shop MAU Williston District Bldgs Williston District Bldgs Energy Mai		expectancy. The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert					\$34,000			\$34,000	
Bldgs Valley City District Bldgs Valley City District Bldgs Williston District Bldgs Williston District Bldgs Energy Mai		The district staff identified this project that they would like added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert									
Bldgs Valley City District Bldgs Valley City District Bldgs Williston District Bldgs Williston District Bldgs Energy Mai		added to their project list. The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert									
Valley City District Bldgs Valley City District Bldgs Williston District Bldgs Williston District Energy Mai	Furnaces with Central Systems	The furnaces in the facility vary in age, but a common theme was there is no zoning of the furnaces	Alert	1.6	\$0	\$0	\$0	\$46,250				
Valley City District Bldgs Williston District Bldgs Williston District Energy Mai	Furnaces with Central Systems	was there is no zoning of the furnaces	Alert									
Valley City District Bldgs Williston District Bldgs Williston District Energy Ma		_		3.1	-\$115	\$0	-\$115	\$518,000			\$518,000	
Williston District Bldgs Williston District Energy Mai												
Williston District Bldgs Williston District Energy Mai		creating temperature control issues. The Reznor make up air handling unit that serves the shop									¢74.000	
Williston District Bldgs Williston District Energy Mai		has exceeded its life expectancy. A new make up air handling									\$74,000	
Williston District Bldgs Williston District Energy Mai	AU Replacement	unit should be sized properly for the shop to replace this unit.		3.1	-\$1,645	\$0	-\$1,645	\$74,000				
Bldgs Energy Mai Williston District Energy Mai		unit should be sized properly for the shop to replace this unit.			7 = 7 5 15	7 -	' ' ' ' '	, , , , , , , ,				
Bldgs Energy Mai Williston District Energy Mai												
Bldgs Energy Mai Williston District Energy Mai		The control system is from 2007 as is most of the equipment										\$0
Williston District Energy Mai	Nanagement and DDC-Base Scope	and sequences. Over time, this equipment becomes out of	Caution	3.8	\$560	\$90	\$650	\$23,250	23.1			
	management and DDC-Dase Scope	calibration and programming can be optimized with new	Caution	3.0	7500	\$30	7030	723,230	23.1			
		strategies.										
Bldgs	Nanagement and DDC-Enhanced Scope	Same as C.10a.	Caution	3.4	\$560	\$90	\$650	\$86,500				\$0
Williston District Lighting Re	Retrofit - Base Project	A majority of the building utilizes fluorescent lighting	Alert	4.5	\$4,355	\$880	\$5,235	\$62,000	10.0		\$0	
Bldgs	Retiont - base Project	technology, including bulbs and ballasts.	Alert	4.5	74,333	7000	75,255	302,000	10.0		ŞU	
	Retrofit - Enhanced Project	Same as E.17a.	Alert	4.4	\$4,400	\$880	\$5,280	\$67,500	10.6		\$0	
Bldgs	•				. ,		. ,	, ,			Ψ.	
Williston District Electrical D	l Distribution Upgrade	The electrical distribution was installed in 1962, but staff has	Alert	3.5	\$0	\$0	\$0	\$143,000			\$143,000	
Bldgs		issues with breakers trip often from the										
Williston District Mind D	Donlacement	kitchen. These systems should be planned for upgrading. There are window systems from 1962 around the facility.	A la vea	3.2	\$80	ć٥	\$80	¢402.000		¢402.000		
	Replacement	· ·	Alarm	3.2	\$80	\$0	\$80	\$493,000		\$493,000		
Bldgs		These systems should be planned for future replacement.										
Williston District Concrete R		The sidewalks around the facility are in poor conditions with	Alert	2.5	\$0	\$0	\$0	\$51,750			\$51,750	
Bldgs	Replacement	cracks.							<u> </u>		, 52,7 50	
Williston District Boiler Repl	e Replacement	These boilers should be planned for future replacement with	Caution	2.4	\$70	\$0	\$70	\$124,000				\$124,000
Bldgs		These poliers should be planned for luture replacement with					1					
		higher efficiency boilers.					1	I	1			



NDDOT Facilites Assessment

Facility	Short Description		Asset Condition	Priority	Utility Savings	O&M Savings	Total Savings	Net Cost	Simple Payback	Alarm Condition Remaining	Alert Condition Remaining	Caution Condition Remaining
Williston District Bldgs	Infrared Heat and Unit Heater Replacement	The shop areas are served by these system that were installed in 2007.	Acceptable	1.7	\$0	\$0	\$0	\$32,250				
Williston District Bldgs	Domestic Hot Water Heater Replacement	There are multiple domestic water heaters in the facility of various ages.	Alert	2.7	\$0	\$0	\$0	\$6,200			\$6,200	
Williston District Bldgs	Replace Office AHU	The district staff identified this project that they would like added to their project list.	Caution	2.2	\$0	\$0	\$0	\$24,750				\$24,750
Williston District Bldgs	Condensing Unit Replacement	The district staff identified this project that they would like added to their project list.	Alert	2.7	\$0	\$0	\$0	\$12,500			\$12,500	
										\$2,052,200	\$8,258,675	\$4,020,000

