




# A Highlight of School Facility Conditions in North Dakota


January 2025  
School Construction Coalition













- This hole is underneath a 6th grade classroom.
- Imagine if a student's desk or chair was sitting on that spot.



\$120 of my own money to buy 4 window fans, and yet temps reach nearly 90° in fall & spring.




E X T R E M E S


I don't have any heat in my classroom. From what I understand, the parts for the heating system are so old replacement parts are no longer made and they cannot be repaired anymore.



I bring space heaters from home as it is common for my room to be 50° in the winter.







Ground water enters into boiler room from the walls after flood zone. The typically foods student sit areas within the original 1804 addition.



Water damage on ceiling and wall in boy's locker room

