



Priority	Site	Building	Project	Budget	Budget plus 18% Inflation	Description
1	Camp Hancock	Bread of Life Church	Repair Tower Water Leak	\$ 17,500	\$ 20,650	The tower has developed a water leak that needs repair. If left unrepaired there will be additional structure damage.
1	Camp Hancock	Museum	Lawn Irrigation System	\$ 7,500	\$ 8,850	The lawn is too large to maintain without a irrigation system.
1	Camp Hancock	Museum	Air Conditioning in Upper Level	\$ 20,000	\$ 23,600	The upper level of the museum is very warm without air conditioning. For exhibits and visitor comfort an air conditionong system is needed.
1	Chateau DeMores	Site	Repair Path to Chateau	\$ 17,500	\$ 20,650	The current path is in poor conition, for visitor safety it needs repairs. The foundation is crumbling in some areas. Support for building stabilization is needed.
1	Chateau DeMores	Chateau	Foundation Stabilization	\$ 78,000	\$ 92,040	We will work with a structural engineer. There are numerous small interior and exterior repairs needed. Propose to hire a contractor for 2-3 weeks, plus materials.
1	Chateau DeMores	Chateau	Interior Repairs	\$ 20,000	\$ 23,600	The path is in poor condition, for visitor safety it needs repairs.
1	Chateau DeMores	Site	Repair Path to the Outbuildings	\$ 45,000	\$ 53,100	Requested by the Fire Marshal - Safety Issue
1	Chateau DeMores	Chateau	Upgrade Electrical	\$ 28,000	\$ 33,040	The connection of the Chateau and the Hunting Room has developed a leak. Repair at the wall/shed roof and structure need repair.
1	Chateau DeMores	Chateau	Repair Roofing/Exterior Wall Connection	\$ 32,000	\$ 37,760	With the increase in electric vehicles and minimal options for charging the Chateau Interpretive Center is a prime location for a charging station.
1	Chateau DeMores	Site	EV Charging Station	\$ 67,500	\$ 79,650	Current system is outdated past its lifespan, creates numerous false alarms.
1	Chateau DeMores	Chateau	Replace Security System	\$ 9,000	\$ 10,620	Existing system is not safe for staff or volunteers. Tripping hazard, unsecure.
1	Chateau DeMores	Chateau	Interpretive Railing System	\$ 100,000	\$ 118,000	
1	Chateau DeMores	Interpretive Center	Shade Structure for Patio	\$ 45,000	\$ 53,100	The Chateau site provides excellent scenery for a walking path. A path creates an opportunity for improving individual health. Design is the initial step with construction at a later date.
1	Chateau DeMores	Site	Hiking Trail Design	\$ 185,000	\$ 218,300	Current visitation calls for additional shelters. Existing shelters need updating.
1	Chateau DeMores	Chimney Park	Update and Add Picnic Shelters	\$ 48,000	\$ 56,640	There is interest by the National Park and the Chateau to create bridge. It creates additional site use and visitation for both entities.
1	Chateau DeMores	Chimney Park	Bridge to the National Park	\$ 17,500	\$ 20,650	The Chateau becomes very warm inside during the summer months. Ductless air conditioning units offer an excellent opportunity to provide air conditioning in the Chateau.
1	Chateau DeMores	Chateau	Add Ductless Air Conditioners	\$ 48,000	\$ 56,640	Housing opportunities in Medora for seasonal staff or vendors is very limited. Creating a small camping area will provide additional opportunities.
1	Chateau DeMores	Caretaker's Cottage/Maintenance Shop	Restore Existing Path and Add Gravel	\$ 12,500	\$ 14,750	The existing septic system is in poor condition and needs replacement.
1	Chateau DeMores	Site	Create Small Campsite/Pad	\$ 15,000	\$ 17,700	
1	Chateau DeMores	Caretaker's Cottage	Septic System	\$ 20,000	\$ 23,600	
1	Chateau DeMores	Site	Public Rest Room	\$ 150,000	\$ 177,000	The current rest room facility near the Chateau is an outhouse and is not visitor friendly.
1	Chateau DeMores	Chateau	Restore/Replace Wallpaper	\$ 47,500	\$ 56,050	The existing wallpaper is in poor condition and replacement is needed.
1	Chateau DeMores	Chateau	Restore/Replace Wallpaper	\$ 47,500	\$ 56,050	The existing wallpaper is over 20 years old and is in poor condition. Replacement is needed.
1	Former Governors' Mansion	Mansion	Window Sealing	\$ 5,000	\$ 5,900	Providing window sealing will assist in keeping the interior clean and more energy efficient.
1	Former Governors' Mansion	Mansion	Wood Fence Replacement	\$ 23,000	\$ 27,140	The existing wood fence is failing and in poor condition. Replacement is needed.
1	Former Governors' Mansion	Mansion	Exterior Painting	\$ 55,000	\$ 64,900	The Former Governors' Mansion was last painted in 2008. Paint is currently peeling and in poor condition.
1	Former Governors' Mansion	Carriage House	Re-Shingle	\$ 45,000	\$ 53,100	
1	Fort Totten	Gymnasium	Gymnasium Restoration	\$ 1,750,000	\$ 2,065,000	The condition of the interior in the gymnasium is poor. Restoration of this buidng will provide the Devils Lake area an additional event space and be an asset to the site, community, and state.
1	Fort Totten	Chaplain & Surgeon Quarter's	Restore Interior	\$ 265,000	\$ 312,700	The condition of the interior of the Chaplain & Surgeon's Quarter's is poor. Restoration of this building will provide visitor's to the site an additional exhibit space and structure to view at the site.

1 Fort Totten	Girl's Dorm	Window Repairs	\$ 52,000	\$ 61,360	Numerous windows in the Girl's Dorm require repair or replacement. Repair will done where feasible, some new windows will be necessary.
1 Fort Totten	Garage/Shop	Chimney Repair	\$ 12,500	\$ 14,750	The chimney at the garage/shop is failing and needs repair. The concrete block is and broken in some locations.
1 Fort Totten	All Buildings	Re-Key	\$ 10,000	\$ 11,800	The exterior doors need to be re-keyed to allow a consistent keying system.
1 Fort Totten	All Buildings	Repair/Replace Doors & Windows	\$ 48,000	\$ 56,640	Many doors and widows need repair or replacement. Some doors and windows are rotted and failing to keep the structure weather tight.
1 Gingras	Site	Re-Grade due to Silting	\$ 65,000	\$ 76,700	The drainage at the Gingras site does not allow for positive drainage due to many years of silt build-up. This has caused water damage to the buildings.
1 Gingras	Trading Post	Re-Chink Logs	\$ 30,000	\$ 35,400	The chinking of the Trading Post is deteriorated and needs replacement. If not completed the logs will begin rotting and require replacement.
1 Gingras	House	Replace Windows	\$ 36,000	\$ 42,480	The existing windows in the house are in poor condition. Repair or replacement is necessary to retain the integrity of the structure.
1 Gingras	Site	Public Restroom	\$ 150,000	\$ 177,000	Currently, the Gingras Historic Site does not provide a rest room facility. Visitors would need to go into Walhalla when a rest room is needed.
1 Welk Homestead	Barn	Stabilize Barn	\$ 325,000	\$ 383,500	The barn at the Welk Homestead is in poor condition structurally. Please see the attached Structural Investigation by Solein-Larson Engineers.
1 Welk Homestead	Site	Picket fence	\$ 15,000	\$ 17,700	Historically a picket fence surrounding the house existed. This proposed project would be to re-construct the fence in its original location and design.
1 Welk Homestead	Site	Public Restroom	\$ 150,000	\$ 177,000	Currently, the Welk Homestead site provides a porta-potty as their rest room facility. This project would provide a modern, permanent facility.
1 Welk Homestead	House	Patch plaster, paint, wallpaper	\$ 50,000	\$ 59,000	The interior of the Welk home needs repair of the plaster walls and repainting. Historically, some walls were wallpapered, this project would re-create that wallcovering in appropriate locations.
1 Fort Buford	Field Officer's Quarters	Replace Fire Suppression Water Tank	\$ 83,000	\$ 97,940	The existing underground tank leaks and is unreliable. When the system does not have water pressure, it creates an air lock that locks up the fire pump. The proposed tank is fiberglass and Nova fire protection has indicated it will not leak. Without the new tank, the fire suppression system is very unreliable.
1 Fort Buford	Public Restroom	Exterior Painting	\$ 15,000	\$ 17,700	Painting of the structure is a necessary maintenance need.
1 Fort Buford	Site	Retaining Wall Construction	\$ 80,000	\$ 94,400	The retaining wall repair is necessary due to erosion, slumping near the interpretive center.
1 MYCIC	Site	Repair Slumping/Erosion	\$ 250,000	\$ 295,000	The site of the Missouri Yellowstone Confluence Interpretive Center has developed a slumping/erosion issue needing repairs.
1 Lewis & Clark Interpretive Center	Lewis & Clark Interpretive Center	Repair to roof and wall in Event Center	\$ 24,000	\$ 28,320	Currently there is a leak at the wall/roof connection of the building. The issue damages interior finishes and has created a mold issue in the building.
1 Lewis & Clark Interpretive Center	Lewis & Clark Interpretive Center	Improve Roof Ventilation	\$ 15,000	\$ 17,700	Some areas of the roof do not have proper ventilation which has created interior finish damage and mold issues.
1 Lewis & Clark Interpretive Center	Lewis & Clark Interpretive Center	Insulate Roof in Fort Clark Gallery	\$ 48,000	\$ 56,640	The Fort Clark Gallery roof does not contain adequate insulation, creating heating and cooling inefficiencies.
1 Fort Mandan	Fort	Architect	\$ 20,000	\$ 23,600	An architects design will be necessary for the fort roof replacement project.
1 Fort Mandan	Fort	Replace Roof	\$ 175,000	\$ 206,500	Due to constant leaks and poor design replacing the roof of the fort is necessary.
1 Fort Mandan	Fort	Drainage Improvement Design	\$ 25,000	\$ 29,500	The drainage of the interior space at the fort is in need of improvement. It is currently poorly designed and floods after snow melt and heavy rains.
1 Fort Mandan	Fort	Drainage Improvements	\$ 80,000	\$ 94,400	The drainage of the interior space at the fort is in need of improvement. It is currently poorly designed and floods after snow melt and heavy rains.
1 Fort Mandan	Site	River Bank Stabilization Design	\$ 25,000	\$ 29,500	A section of the river bank west of Fahlgren Park has some erosion that requires stabilization. Working with an engineer on design will be necessary.
1 Fort Mandan	Site	Stabilize River Bank	\$ 250,000	\$ 295,000	This request is for the construction of the river bank stabilization.
1 Fort Mandan	Visitors Center	Replace Heat Pump	\$ 12,000	\$ 14,160	One of the heat pumps at the visitor center will require replacement due to age.
1 Fort Mandan	Visitor Center	Replace Carpet in Lodge Classroom	\$ 12,000	\$ 14,160	The existing carpet is in poor condition with many stains that cleaning will not resolve.
1 Fort Mandan	Fort	Repair/Replace Gate & Logs	\$ 32,000	\$ 37,760	The entrance gate and a number of the logs require repair or replacement. The gate is sagging badly and is very difficult for staff to open and close. Some logs are rotted and require replacement.

1 Fort Mandan	Fort	Re-chink logs	\$ 75,000	\$ 88,500	The current chinking is in poor condition and not the correct material. Replacement is necessary to eliminate moisture penetratin and rotting of the structure.
1 Fort Mandan	Site	Remove Roadbuilding Waste @ Park	\$ 15,000	\$ 17,700	Unightly roadbuilding waste was dumped west of Fahlgren Park over a number of years. It creates a dangerous situation with children in the nearby park.
1 Fort Mandan	Fort	Upgrade Electrical	\$ 12,500	\$ 14,750	The fort has very few electrical outlets. Overloading of circuits and extremely long use of extension cords is unsafe and a hazard.
1 Stutsman County Courthouse	Courthouse	Airconditioning	\$ 35,000	\$ 41,300	Currently, the courthouse does not have an air conditioning system. During the summer months it gets very warm and uncomfortable in the building. The courthouse is visited as a historic site and also used by Stutsman County for some court cases.
1 Whitestone Hill	Site	Repair/Replace Footbridge	\$ 15,000	\$ 17,700	The existing footbridge is in poor condition. It is necessary to provide access to the picnic shelter for visitors. Repair or replacement is necessary.
1 Whitestone Hill	Well House	Replace Roof	\$ 5,000	\$ 5,900	The roof is in poor condition, it has not been replaced in over 20 years.
1 Whitestone Hill	Monument	Clean Bugler Monument	\$ 10,000	\$ 11,800	
1 Whitestone Hill	Site	Restore WPA Stone Path	\$ 28,000	\$ 33,040	
1 Whitestone Hill	Site	Replace Cemetary Fence	\$ 15,000	\$ 17,700	
1 Whitestone Hill	Site	Resurface Roadway	\$ 85,000	\$ 100,300	
1 Whitestone Hill	Office/House	Interior Restoration	\$ 112,500	\$ 132,750	The interior of the office/house is in very poor condition. It is currently a hazard for the site supervisor's use. There is a mold issue and mice have utilized it as their home. The mice have caused numerous issues in the office.
1 Whitestone Hill	Site	Public Restroom	\$ 150,000	\$ 177,000	The onsite restrooms are vault toilets that are in poor condition.
1 Fort Clark	Site	Public Restroom & Water Shutoff	\$ 150,000	\$ 177,000	The Fort Clark site does not currently provide a public restroom. Visitors would need to leave the site to find a restroom if needed.
1 Fort Rice	Shelter	Foundation Repairs	\$ 40,000	\$ 47,200	The existing foundation is in poor condition, repairing the foundation is necessary for preservation of the shelter.
1 Fort Rice	Shelter	Roof Replacement	\$ 10,000	\$ 11,800	The existing roof is in poor condition, replacing the roof is necessary for preservation of the structure.
1 Molander Indian Village	Site	Cattle Guard @ New Entrance	\$ 40,000	\$ 47,200	
1 Huff	Kiosk	Roof Replacement	\$ 10,000	\$ 11,800	The existing roof is in poor condition, replacing the roof is necessary for preservation of the structure.
1 AHP Shop	AHP Shop	Roof Repair	\$ 12,500	\$ 14,750	The existing roof is in poor condition, replacing the roof is necessary for preservation of the structure.
1 AHP Shop	AHP Shop	Foundation Repairs	\$ 50,000	\$ 59,000	The existing foundation stabilization due to a water main leak that has been repaired. The existing doors are in poor condition. Replacement is needed due to operation of the doors, door condition, and age.
1 AHP Shop	AHP Shop	Replace Entrance Doors (2)	\$ 12,500	\$ 14,750	
1 Menoken	Site	Public Restroom	\$ 150,000	\$ 177,000	Currently, the Menoken Indian Village site does not provide a public restroom. A visitor needs to leave the site and go elsewhere to use the restroom.
1 Pembina State Museum	Pembina State Museum	Exterior Cleaning and Painting	\$ 48,000	\$ 56,640	The Pembina State Museum was constructed in 1995 and has not been re-painted. The existing paint is peeling and in poor condition.
1 Pembina State Museum	Pembina State Museum	Interior Improvements	\$ 50,000	\$ 59,000	Numerous interior improvements are needed in the museum. It has not been updated since original construction in 1995.
1 Pembina State Museum	Pembina State Museum	Replace Humidifiers	\$ 75,000	\$ 88,500	
1 Pembina State Museum	Pembina State Museum	Exterior Signage	\$ 50,000	\$ 59,000	Additional visability from the Interstate will increase visitation.
1 Pembina State Museum	Pembina State Museum	New Heat Pumps	\$ 35,000	\$ 41,300	The existing heat pumps have outlived their life expectancy. These are the last of the original heatpumps that need replacement.
1 Double Ditch	Site	Public Rest Room	\$ 150,000	\$ 177,000	Currently, the Double Ditch site does not provide a public restroom. A visitor needs to leave the site and go elsewhere to use the restroom.
			<b>\$ 6,751,500</b>	<b>\$ 7,966,770</b>	





Camp Hancock - Air Conditioning



Chateau - Foundation Stabilization



Chateau - Foundation Stabilization



Chateau - Path to Chateau



Chateau - Path to Out Buildings



Former Governors' Mansion - Exterior Painting



Former Governors' Mansion - Exiting Fence Wood Rotting



Fort Totten - Gymnasium Interior



Fort Totten - Interior of the Surgeon's Quarters



Fort Totten - Girl's Dorm Window Replacement



Fort Totten - Shop Chimney Repair



Gingras - Window Replacement Siding Replacement upcoming in 2022



Gingras - Window Replacement



Gingras - Window Replacement



Lewis & Clark Interpretive Center - Event Center





Welk Home - Plaster Repair



Welk Home - Plaster Repair



Welk Barn - Stabilization



Welk Barn - Stabilization



Fort Mandan - Gate, Drainage & Roof Replacement



Fahlgren Park - Road Debris





Whitestone Hill - Footbridge



Pembina State Museum - Signage Request

2	Camp Hancock	Museum	Penthouse Observation Platform	\$	56,000	\$	66,080	Phase 3
2	Chateau DeMores	Chateau	Restore/Replace Wallpaper	\$	47,500	\$	56,050	Phase 4
2	Chateau DeMores	Chateau	Restore/Replace Wallpaper	\$	47,500	\$	56,050	
2	Chateau DeMores	Chateau	Restore Floor and Replace Carpet Runner	\$	32,000	\$	37,760	
2	Chateau DeMores	Chateau	Paint Exterior	\$	48,000	\$	56,640	
2	Chateau DeMores	Chateau	Paint Roof	\$	14,500	\$	17,110	
2	Chateau DeMores	Site	Water Line Trenched to Outbuildings	\$	8,000	\$	9,440	Interpretive Center
2	Chateau DeMores	Site	Parking Lot Repairs/Resurface	\$	125,000	\$	147,500	Chateau Parking Lot
2	Chateau DeMores	Site	Parking Lot Repairs/Resurface	\$	35,000	\$	41,300	
2	Chateau DeMores	Chateau	Replace Shutters	\$	7,500	\$	8,850	
2	Chateau DeMores	Site	Interpretive Signage	\$	5,000	\$	5,900	
2	Chateau DeMores	Chimney Park	Upgrade Electrical System	\$	12,500	\$	14,750	
2	Chateau DeMores	DeMores Park	Landscaping	\$	18,000	\$	21,240	
2	Chateau DeMores	Interpretive Center	Landscaping	\$	24,000	\$	28,320	
2	Chateau DeMores	Carriage House	Repair/Replace Floor	\$	10,000	\$	11,800	
2	Chateau DeMores	Carriage House	Interpretive Railing System	\$	85,000	\$	100,300	Phase 1
2	Chateau DeMores	Site	Hiking Trail in the River Bottom	\$	451,440	\$	532,699	Phase 2
2	Chateau DeMores	Site	Hiking Trail in the River Bottom	\$	451,440	\$	532,699	Build stalls, ADA access, Interpretive signage
2	Chateau DeMores	Stable	Interior Restoration	\$	15,000	\$	17,700	
2	Chateau DeMores	Chimney Park	Build a Structure for Interpretation	\$	35,000	\$	41,300	
2	Chateau DeMores	Chateau	Replace Rain Gutter System	\$	4,500	\$	5,310	
2	Chateau DeMores	Shed	Add Rain Gutter System	\$	2,500	\$	2,950	
2	Former Governors' Mansion	Site	Lawn Irrigation System	\$	6,000	\$	7,080	Phase 2
2	Former Governors' Mansion	Mansion	Wall Papr Replacement	\$	47,500	\$	56,050	
2	Former Governors' Mansion	Mansion & Carriage House	Energy Efficiency Improvements	\$	5,000	\$	5,900	
2	Fort Totten	Hospital	Re-Shingle (Cedar Shingles)	\$	105,000	\$	123,900	
2	Fort Totten	Adjutant's Office	Exterior Painting	\$	34,500	\$	40,710	
2	Fort Totten	Visitor Center	Exterior Painting	\$	52,500	\$	61,950	
2	Fort Totten	Girl's Dorm	Exterior Painting	\$	61,000	\$	71,980	
2	Fort Totten	Sewing/Tailor Shop Upper Level	Restore Interior	\$	146,300	\$	172,634	
2	Fort Totten	Girl's Dorm Upper Level	Restore Interior	\$	279,900	\$	330,282	
2	Fort Totten	Commanding Officer's Qtrs Upper Level	Restore Interior	\$	126,000	\$	148,680	
2	Fort Totten	Print Shop Upper Level	Restore Interior	\$	143,000	\$	168,740	Architect for Upper Level of Hospital, Boy's Dorm & Little Theater
2	Fort Totten	Hospital, Boy's Dorm, Little Theater	Architect	\$	120,000	\$	141,600	
2	Fort Totten	Tailor Shop	Exterior Painting	\$	34,000	\$	40,120	
2	Fort Totten	Commanding Officer's Quarters	Exterior Painting	\$	38,500	\$	45,430	
2	Fort Totten	Totten Trail Inn	Exterior Painting	\$	46,000	\$	54,280	
2	Fort Totten	Print Shop	Exterior Painting	\$	34,500	\$	40,710	
2	Fort Totten	Chaplain & Surgeon's Quarters	Exterior Painting	\$	38,000	\$	44,840	
2	Fort Totten	Boys Dorm	Restore Shower Room Interior	\$	151,200	\$	178,416	Check w. Bill. Need to talk to neighbors who are currently farming the land
2	Gingras	Site	Fence 12.82 acres of property	\$		\$	-	
2	Gingras	Site	Tallgrass prairie restoration on 12.82 acres	\$		\$	-	
2	Gingras	Site	Interpretive trail on 12.82 acres of property	\$		\$	-	
2	Gingras	Site	Exterior Lighting	\$	15,000	\$	17,700	Asked Brian to confirm condition

2	Welk Homestead	House, summer kitchen, blacksmith shop, gra	Reshingle (cedar shakes)	\$	-		
2	Welk Homestead	Site	Shelter Belt Restoration	\$	15,000	\$ 17,700	
2	Welk Homestead	Site	Exterior Event Space	\$	86,500	\$ 102,070	
2	Welk Homestead	Site	Dock	\$	10,000	\$ 11,800	
2	Fort Buford	Site	Walking Path Resurface	\$	488,700	\$ 576,666	
2	Fort Buford	Barracks	Replace Interior Beams			\$ -	
2	MYCIC	Site	ParkingLot Repairs/Resurface	\$	125,000	\$ 147,500	
2	MYCIC	Site	Walking Path	\$	293,040	\$ 345,787	
2	MYCIC	Site	Walking Path Design (MYCIC & Fort Buford)	\$	80,000	\$ 94,400	
2	Lewis & Clark Interpretive Center	Lewis & Clark Interpretive Center	Replace/Upgrade Fire Alarm System	\$	20,000	\$ 23,600	It has both flat roofs and asphalt shingles.
2	Fort Mandan	Visitor Center	Re-roof visitor center	\$	17,500	\$ 20,650	
2	Fort Mandan	Visitor Center	Refinish Flooring/Cleaning	\$	10,000	\$ 11,800	
2	Fort Mandan	Visitor Center	Upgrade Electrical Controls	\$	5,000	\$ 5,900	
2	Fort Mandan	Visitor Center	Improve Acoustics in Play Space	\$	15,000	\$ 17,700	
2	Stutsman County Courthouse	Courthouse	Window Repairs/Replace	\$	28,000	\$ 33,040	
2	Stutsman County Courthouse	Courthouse	Basement Restoration	\$	85,000	\$ 100,300	
2	Stutsman County Courthouse	Courthouse	Upgrade Tower Lighting and Outlets	\$	32,000	\$ 37,760	
2	Whitestone Hill	Site	Replace Payground Equipment	\$	85,000	\$ 100,300	
2	Whitestone Hill	Site	Dock	\$	10,000	\$ 11,800	440v, 240v
2	RRMMS	Site	EV Charging Station	\$	67,500	\$ 79,650	
2	Pembina State Museum	Pembina State Museum	Fresh Air/Exhaust Improvement			\$ -	
2	Pembina State Museum	Pembina State Museum	Outdoor Event Space & Picnic Shelter	\$	60,000	\$ 70,800	
2	Pembina State Museum	Pembina State Museum	Landscaping	\$	23,000	\$ 27,140	440v, 240v
2	Pembina State Museum	Pembina State Museum	EV Charging Station	\$	67,500	\$ 79,650	
2	Pembina State Museum	Pembina State Museum	Playground Equipment	\$	85,000	\$ 100,300	
2	Double Ditch	Site	Entry & Parking Lot Improvements	\$	150,000	\$ 177,000	
2	Writing Rock	Picnic Shelter	Repair to Roof Trusses & Sheathing	\$	20,000	\$ 23,600	
2	Writing Rock	Shed	Replace shed building			\$ -	
2	Writing Rock	Writing Rock Structure	Repairs			\$ -	
2	Writing Rock	Site	Water Pump			\$ -	
				<b>\$</b>	<b>4,898,020</b>	<b>\$ 5,779,664</b>	

3	Camp Hancock	Bread of Life Church	Paint Exterior	\$	38,000	\$ 44,840	
3	Camp Hancock	Museum	Paint Exterior	\$	46,000	\$ 54,280	
3	Chateau DeMores	Site	Restore/Replace Site Bridge	\$	15,000	\$ 17,700	
3	Chateau DeMores	Site	Repair erosion issue @ Ravine	\$	18,000	\$ 21,240	
3	Chateau DeMores	Site	Repair/Replace Fence by Outbuildings	\$	12,500	\$ 14,750	
3	Chateau DeMores	Site	Reconstruct Greenhouses	\$	12,000	\$ 14,160	
3	Chateau DeMores	Garage/Maintenance Shop	Replace Overhead Doors	\$	8,500	\$ 10,030	Phase 3
3	Chateau DeMores	Site	Hiking Trail in the River Bottom	\$	451,440	\$ 532,699	Phase 4
3	Chateau DeMores	Site	Hiking Trail in the River Bottom	\$	451,440	\$ 532,699	
3	Former Governors' Mansion	Mansion	Floor Refinishing	\$	15,000	\$ 17,700	Phase 3
3	Former Governors' Mansion	Mansion	Wall Papr Replacement	\$	47,500	\$ 56,050	Phase 4
3	Former Governors' Mansion	Mansion	Wall Papr Replacement	\$	47,500	\$ 56,050	
3	Former Governors' Mansion	Mansion	Basement Restoration	\$	70,000	\$ 82,600	
3	Former Governors' Mansion	Carriage House	Exterior Painting	\$	28,500	\$ 33,630	
3	Former Governors' Mansion	Carriage House	Interior Painting	\$	18,000	\$ 21,240	
3	Fort Totten	Chaplain & Surgeon's Qtrs Upper Level	Restore Interior	\$	132,000	\$ 155,760	
3	Fort Totten	Hospital Upper Level	Restore Interior	\$	382,000	\$ 450,760	
3	Fort Totten	Boys Dorm Upper Level	Restore Interior	\$	450,000	\$ 531,000	
3	Fort Totten	Little Theater Upper Level	Restore Interior	\$	363,000	\$ 428,340	440v, 240v
3	Fort Totten	Site	EV Charging Station	\$	67,500	\$ 79,650	
3	Fort Totten	Hospital	Exterior Painting	\$	44,500	\$ 52,510	
3	Fort Totten	Quartermaster's Building	Exterior Painting	\$	28,500	\$ 33,630	
3	Fort Totten	Boy's Dorm	Exterior Painting	\$	53,000	\$ 62,540	

3 Fort Totten	Gymnasium	Exterior Painting	\$ 43,000	\$ 50,740	
3 Fort Totten	Little Theater	Exterior Painting	\$ 49,000	\$ 57,820	
3 Fort Totten	Shop	Exterior Painting	\$ 24,000	\$ 28,320	
3 Gingras	House	Paint Interior	\$ 12,000	\$ 14,160	440v, 240v
3 Gingras	Site	EV Charging Station	\$ 67,500	\$ 79,650	440v, 240v
3 Fort Abercrombie	Site	EV Charging Station	\$ 67,500	\$ 79,650	
3 Welk Homestead	Site	Exterior Lighting	\$ 10,000	\$ 11,800	440v, 240v
3 Welk Homestead	Site	EV Charging Station	\$ 67,500	\$ 79,650	
3 Fort Buford	Field Officer's Quarters	Exterior Painting	\$ 38,000	\$ 44,840	
3 Fort Buford	Barracks	Exterior Painting	\$ 34,000	\$ 40,120	
3 Fort Buford	Officer of the Guard	Exterior Painting	\$ 12,000	\$ 14,160	440v, 240v
3 MYCIC	Site	EV Charging Station	\$ 67,500	\$ 79,650	
3 MYCIC	MYCIC	Tuckpointing	\$ 28,000	\$ 33,040	
3 MYCIC	MYCIC	Retaining Wall Repair	\$ 8,000	\$ 9,440	
3 Lewis & Clark Interpretive Center	Lewis & Clark Interpretive Center	Upgrade Electrical Controls	\$ 7,500	\$ 8,850	
3 Stutsman County Courthouse	Courthouse	Re-Shingle (Cedar Shingles)	\$ 125,000	\$ 147,500	440v, 240v
3 Fort Clark	Site	EV Charging Station	\$ 67,500	\$ 79,650	
3 RRMMS	Site	Repair/Replace Exterior Lighting		\$ -	Need to work with a Solar Panel Technician/Designer
3 Pembina State Museum	Pembina State Museum	Solar Panels		\$ -	
			<b>\$ 3,527,880</b>	<b>\$ 4,162,898</b>	