CHAPTER 90-02-03 REPORTING AND OPERATIONS

Section

90-02-03-01	Completion Reports Required to Be Filed
~~ ~~ ~~ ~~	

90-02-03-02 Filing Reports

90-02-03-03 In Charge - Definition [Repealed]

90-02-03-04 Decal Required

90-02-03-01. Completion reports required to be filed.

The secretary-treasurer shall develop and supply well completion reporting forms as required by North Dakota Century Code section 43-35-19.

History: Amended effective October 1, 2024.

General Authority: NDCC 43-35-10 **Law Implemented:** NDCC 43-35-19

90-02-03-02. Filing reports.

The secretary-treasurer shall maintain a systematic file of well completion reporting forms.

History: Amended effective October 1, 2024.

General Authority: NDCC 43-35-10 **Law Implemented:** NDCC 43-35-19

90-02-03-03. In charge - Definition.

Repealed effective October 1, 2024.

90-02-03-04. Decal required.

Any water well equipment, pump and pitless unit equipment, geothermal equipment, or monitoring well equipment operating in North Dakota must prominently display a decal on the primary equipment that is under the charge of a certificate holder. Before beginning any water well equipment, pump and pitless unit equipment, geothermal equipment, or monitoring well equipment operation, the certificate holder in charge shall secure a decal from the board and place it on the primary equipment.

History: Amended effective May 1, 2002; October 1, 2024.

General Authority: NDCC 43-35-10 **Law Implemented:** NDCC 43-35-16