Sixty-seventh Legislative Assembly of North Dakota

HOUSE BILL NO. 1229

Introduced by

Representatives Satrom, Heinert, Schauer

Senator Conley

- 1 A BILL for an Act to amend and reenact section 39-21-39 of the North Dakota Century Code,
- 2 relating to tinted windows; and to provide a penalty.

3 BE IT ENACTED BY THE LEGISLATIVE ASSEMBLY OF NORTH DAKOTA:

4 SECTION 1. AMENDMENT. Section 39-21-39 of the North Dakota Century Code is

5 amended and reenacted as follows:

39-21-39. Windshield - Must be unobstructed and equipped with wipers - Tinted windows.

- A motor vehicle must be equipped with a windshield. An individual may not drive anya
 motor vehicle with any sign, poster, or other nontransparent material uponon the front
 windshield, side wings, or side or rear windows which obstructs the driver's clear view
 of the highway or any intersecting highway.
- The windshield on a motor vehicle must be equipped with a device for cleaning rain,
 snow, or other moisture from the windshield, which must be constructed as to be
 controlled or operated by the driver of the vehicle.
- 15 3. The windshield wiper upon a motor vehicle must be maintained in good working order.
- An individual may not operate a motor vehicle with any object, material, or tinting
 displayed, affixed, or applied on the front windshield or any window unless the object,
 material, or tinting in conjunction with the windshield upon which it is displayed,
- 19 affixed, or applied has a light transmittance of at least no less than seventy percent or
- 20 the object, material, or tinting in conjunction with a window other than the windshield
- 21 upon which it is displayed, affixed, or applied has a light transmittance of at leastno
- 22 <u>less than fifty percent</u>. This subsection does not apply to windows Windows behind the
- 23 operator if may not have less than thirty-five percent light transmittance unless the
- 24 motor vehicle was equipped with tinted or privacy glass by the manufacturer when

Sixty-seventh Legislative Assembly

- 1 <u>built and</u> the motor vehicle is equipped with outside mirrors on both sides that which
- 2 meet the requirements of section 39-21-38.