

Brynchild Haugland upper entrance



- No signage indicating room location or accessibility
- I accidentally found this door, but prior to, avoided the room when possible, as I did not want to sit on the “bottom” and/or use the elevator
- Is Brynchild Haugland included in HB1510, HB1030 and SB2146?

Capitol Accessibility Photos

Jillian Schaible

Brynchild Haugland bathroom entrance



- Stair door to ground floor men's bathroom
- There is a room behind the door, but this door blocks it

Brynhild Haugland



- Inside ground floor men's bathroom

Brynchild Haugland




- Both TVs outside both entrances are too high
- Wheelchair elevator is located here

Brynhild Haugland Elevator




- Installed when?
- Who maintains it?
- How often is it checked?

Brynchild Haugland second entrance



- TV height too high

Harvest Room Entrance



- TV height is too high

Horseshoe Rooms




- Can the doors remain unchanged?
- What about having a doorbell outside with an indicator light? When it goes off someone could open both doors
- Can we stream committee hearings on these TVs?
- All TVs appear to be the same height; no changes made to doors

Lewis and Clark



- TV height too high
- Very narrow door

Ground Floor Men's Bathroom A



- Accessibility signage too high
- There is another sign on the opposite wall at the same height

Ground Floor Men's Bathroom A




- Accessible entrance
- All accessibility signage should be at the same level everywhere

Ground Floor Men's Bathroom A



- Accessible entrance view
- Trash can should not be underneath dispenser
- Same view from stair door

Ground Floor Men's Bathroom A



- Is the stall wall accessible?
- There are at least two other doors where the sign indicating accessibility is placed on a stall wall and not on the door itself. A visually impaired individual could mistake the wall for the door
- Outside coat hanger could cause injury. Other doors have the same issue
- Lock could be a problem

Ground Floor Men's Bathroom A



- Reverse in, forward to lock door, then position
- Massive space between wall and toilet
- Side transfer may not be possible
- Urinal bar also far away
- There are better accessible urinals and grab bars to have
- Same setup in Ground Floor Men's Bathroom B

Men's Bathroom A



- This is the only horizontal grab bar next to a urinal in an “accessible” area in the building – and it makes the most sense
- There should be a grab bar on both sides for balance and strength dominance assistance
- Install a floor urinal wherever accessible urinals are located

2 mens Bathrooms
1 womens Bathroom

Ground Floor Men's Bathroom A



- [Dyson Airblade 9KJ | Dyson](#)
- \$1,199.00
- HEPA filter (est. \$79/each, requires monitoring/replacing)
- 2 in this bathroom
- 1 in women's ground floor bathroom
- Accessible sink sign
- Paper towel dispenser may be too high

Ground Floor Men's Bathroom B




- No accessibility signage

Ground Floor Men's Bathroom B



- Turning radius may not be legal
- Door may not stay open when trying to get in

Ground Floor Men's Bathroom B



- Looks like the left urinal is attempting to be “accessible”
- Add horizontal grab bars?
- If the entire bathroom is not accessible, accessibility signage should not be used anywhere
- Sink area is not “accessible” as well

Ground Floor Ramp




- The architect said this was not ADA compliant somehow...

Red River Room



- Can access be given without door alterations?
- Good height for the TV
- Similar situation for Sakakawea Room

Roughrider Room




- TV height is too high
- No change to doors

Small Elevator keypads – 37 total




- Who manufactures these?
- When were they installed?
- Do they get tested to ensure they are working properly?
- If so, how often?
- What happens if one breaks?
- Can pressure sensitivity, volume, tone, reaction speed, voice speed be changed?
- Post instructions on how to operate?

Large Elevator keypads – 2 – Ground floor




- Why are these different from the other 37?
- Same questions apply regarding the small elevator keypads

Executive Elevator Screens A, B, C, D



- Can these be programmed to better assist visually/hearing impaired?
- Who programs them?

Ground Floor Senate Bathroom



- Accessibility signage too high
- Also on opposite wall

Ground Floor Senate Bathroom

- Accessible entrance



Ground Floor Senate Bathroom



- Another accessible stall wall?
- There is also a judicial wing bathroom accessible stall missing door signage, but it is on the stall wall
- Why is there no signage on the door, but a coat hanger is?
- Two judicial wing bathrooms have accessibility signage on the inside of the accessible stall door

Ground Floor Senate Bathroom



- Looks like this was 2 stalls – wall with grab bar and toilet removed
- Reverse in, forward to close door, proceed to perhaps block the toilet, depending on need

Ground Floor Senate Bathroom



- Accessible sink and soap dispenser
- Why not cover all sink plumbing?

Ground Floor Senate Bathroom



- Most, if not all, bathrooms in the building have this paper towel dispenser
- Could not find ADA compliance documentation
- Why so far from accessible sink?

Ground Floor West Door



- Automatic door
- Why isn't there one on the Judicial wing entrance/exit door?


Ground Floor West Door Ramp

- Do not remember what the architect said about this ramp




Ground Floor Women's Bathroom

- No accessibility signage



Ground Floor Women's Bathroom



- Why is the signage inside the second door?
- Signage is too high

Ground Floor Women's Bathroom



- Good set up
- Cover all sink plumbing

Ground floor Women's Bathroom



- Reverse in, and pull the door closed at the same time?
- What is with the gaps between the toilet and the grab bar?
- Ripping a stall out is not necessarily “accessible” or “compliant”

House Chamber



- Where are the ramps?
- There are none in the chamber
- The House and Senate chambers were not included in the “accessibility” study done by the architect hired by OMB

Senate Chamber



- Who built the existing ramps admitted to in SGVA testimony on 1.21.21?
- Built when?
- Meet current ADA compliance?
- Why are they not in use in either chamber?

Prairie Room



- Can these doors be opened and unaltered when the room is in use?

Prairie Room



- Change the table before altering room
- Same suggestions about leaving the room doors alone

2nd Floor Offices




- Why are there not two doors here?

Executive Wing Department Floors 3-18



- Accessible signage for Executive wing bathrooms should be removed, as they will not be ADA compliant based on door width alone

Executive Wing Department Floors 3-18



- Signage outside all department doors should be consistent and consider visually impaired
- Sign could be mobility impediment

Executive Wing Department Floors 3-18




- Trash can blocking keypad access
- This occurs on multiple floors

Judicial Wing Elevators



- No keypad
- No accessibility signage
- Poor signage
- Ironic, given this is the “accessible” wing
- Identical occurs on 1st, 2nd and 3rd judicial floors

Senate Elevator – First Floor



- Ground, 1st, 2nd floors
- No accessibility signage
- No external signage on 1st floor

Judicial Wing – bathroom signage



- All judicial wing women's bathrooms

Judicial Wing – bathroom signage



- All judicial wing men's bathrooms

Judicial Wing – bathroom entrance



- Also women's bathroom
- Same set up on 2nd floor men's and women's bathrooms

Judicial Wing – All Elevator Bathrooms



- Cannot access soap without water issue
- This is an issue in all Judicial wing bathrooms by the elevators
- Why not have soap on same wall as paper towels?
- Move a soap dispenser to wall where unused paper towel dispensers are?
- Cover sink plumbing

Judicial Wing – All “accessible” stalls




- Original grab bars
- Bar length should be longer so person won't be blocking toilet before transfer
- Vertical bar would help with this also
- All “accessible” judicial wing stalls have similar set up
- Most, if not all also have a coat hanger close to door lock, which could be a safety hazard and should be on the back of the stall door at an accessible height

Judiciary Wing – “Accessible” urinal




- I do not understand how this can work sitting or standing with a mobility impairment
- Heat register changes access angle
- Similar lay out for all judicial wing “accessible” urinals

Judicial Wing – 1st and 2nd Inside bathrooms



- Difficult to open door with strap in a manual or powered wheelchair
- Need to reverse until there's enough room while still holding strap and driving chair
- How does a person hold the door open as far as they can, AND move through the door unassisted?
- Judicial wing 1st floor men's and women's, 2nd floor women's, not men's

Judicial Wing – 1st Floor



- All 6 bathrooms inside Judicial wing halls have a “first” door with correct signage
- This first door does not meet 5 pound pressure limit standard, or the 3 second rule

Judicial Wing – Hallway Bathrooms




- Door #2
- Occurs with all bathrooms inside Judicial wing hallways
- Trash can obstacle
- Easy to push door going in, may be difficult to open coming out due to counter location

Judicial Wing – 2nd Floor



- Sink and paper towel setup inside all Judicial wing bathrooms
- Cover all sink plumbing

Sheyenne/Coteau Rooms – 1st Floor



- TV height is way too high
- This area is confusing, as there is poor signage
- Coteau is one room now, not two
- TVs next to rooms are at lower height

Judicial Wing – 1st Floor



- Missing door handle, but just think...you can hang your coat up, and not use the bathroom

Judicial Wing – 1st Floor



- “accessible sink”

Judicial Wing – Bathrooms

- Ground floor and third floor men's and women's bathrooms



JWing – Ground Floor



- Move soap to paper towel dispenser to make it easier to reach
- Cover all sink plumbing

JWing – Ground Floor




Judicial Wing – 2nd Floor



- This is the sink and paper towel setup inside all Judicial wing hall bathrooms
- Cover all sink plumbing

Judicial Wing – Women’s Ground Floor



- Missing door handle
- Put in request during 2019 session
- Also missing in women’s 1st floor Judicial wing bathroom

Pioneer Room



- When were the TVs put in?
- Who decided placement and size?

Judicial Wing – 2nd Floor



- Great sign

Judicial Wing – 3rd Floor



- Target (button) does not work on first contact – going in
- Random signage like door signage throughout this floor