



Capitol Interiors




Marble Base




Wood Doors & Frames





Capitol Interiors



Window Sill @ West End of Legislative
Wing showing Cracked Marble and
Delaminated Wood Sill/Jamb